

# Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716  
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg  
 GST:201006949C RCB NO:201006949C

*not authorized  
 mkk  
 mckus  
 20/3/23  
 1/5 25800  
 4 days*

M/S : SOMPO INSURANCE SINGAPORE PTE. LTD  
 50 Raffles Place  
 Singapore Land Tower #05-01/06  
 Singapore 048623  
 TEL: 64616555 FAX: 62213302  
 ATTN: Motor Claim Department \ SOMPO

Estimate No: EST1509318  
 Date: 10 Feb 2023  
 Policy No: P10266655R03  
 Veh Reg No: SLH1697Z  
 Make/Model: NISSAN X-TRAIL 2.0  
 CVT ABS 4WD S/R 7-STR  
 Chassis No: JN1JANT32Z0002647  
 Engine No: MR20904251B  
 Reg. Date: 26/10/2016

Your Ref No: TP 0223-7260  
 Claim Type: Third Party  
 Accident Date: 10/02/2023  
 TP Veh Reg No: SFU6556S

## Estimate Repair Cost to Vehicle No :SLH1697Z

Description	U/Price	Quantity	Price	Amount
			SS	SS
<b>List Price</b>				
1 REAR BUMPER WITH LOWER BLACK	693.1000	1 PC	693.10	—
2 REAR BUMPER SIDE HOLDER - LH/RH	47.1000	2 PC	94.20	—
3 REAR BUMPER CLIPS	<del>5.0000</del>	<del>10 PC</del>	<del>50.00</del>	—
4 REAR BUMPER REFLECTORS - LH/RH	61.3000	2 PC	122.60	X
5 REAR BUMPER REINFORCEMENT	596.2000	1 PC	596.20	—
6 REAR BUMPER LOWER CENTER GRILLE (BLACK)	127.0000	1 PC	127.00	X
7 REAR END PANEL	447.5000	1 PC	447.50	X
8 REAR END PANEL TOP GARNISH	87.8000	1 PC	87.80	X
9 BOOTLID	4,380.0000	1 PC	4,380.00	—
10 BOOTLID XTRAIL WORDINGS	94.0000	1 PC	94.00	—
11 BOOTLID GLASS MOULDING	106.3000	1 PC	106.30	—
12 BOOTLID NISSAN LOGO	94.0000	1 PC	94.00	X
13 BOOTLID RUBBER	140.8000	1 PC	140.80	X
			7,033.50	
			Less 10%	6,330.15
<b>Special Net</b>				
14 REAR BUMPER SENSOR (4PCS)	400.0000	1 PC	400.00	400.00
<b>Labour</b>				
15 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS	800.0000	1 JOB	800.00	480
16 TO RESPRAY PAINT ON ACCIDENT PORTIONS (BUMPER 3 COLOUR)	900.0000	1 JOB	900.00	600
17 TO CHECK WIRING	40.0000	1 JOB	40.00	20
18 TO REMOVE, REFIT REAR GLASS	180.0000	1 JOB	180.00	120
19 TO REMOVE, REFIT REAR GARNISH TO FACILITATE REPAIR	150.0000	1 JOB	150.00	60
20 TO REMOVE, REPLACE REAR BUMPER SENSOR	90.0000	1 JOB	90.00	50
21 TO TUFF-KOTE	60.0000	1 JOB	60.00	X
			2,220.00	2,220.00

*2 pcs 14. Rear bumper brackets e*

*sent*

*1 set 1 PC shock 400.00 200 S/N*

# Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716  
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg  
GST:201006949C RCB NO:201006949C

**M/S :** SOMPO INSURANCE SINGAPORE PTE. LTD

50 Raffles Place  
Singapore Land Tower #05-01/06  
Singapore 048623

TEL: 64616555 FAX: 62213302

ATTN: Motor Claim Department \ SOMPO

**Estimate No:** EST1509318

**Date:** 10 Feb 2023

**Policy No:** P10266655R03

**Veh Reg No:** SLH1697Z

**Make/Model:** NISSAN X-TRAIL 2.0  
CVT ABS 4WD S/R 7-STR

**Chassis No:** JN1JANT32Z0002647

**Engine No:** MR20904251B

**Reg. Date:** 26/10/2016

Your Ref No: TP 0223-7260

Claim Type: Third Party

Accident Date: 10/02/2023

TP Veh Reg No: SFU6556S

## Estimate Repair Cost to Vehicle No :SLH1697Z

Description	U/Price	Quantity	Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	SS 8,950.15
			Add GST @ 8%	716.01
			Total Amount Payable	SS 9,666.16

TOTAL: SINGAPORE DOLLAR NINE THOUSAND SIX HUNDRED SIXTY SIX AND CENTS SIXTEEN ONLY

9304.38

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

