



Boxfresh Pte Ltd

7030 Ang Mo Kio Ave 5 #06-49
 Northstar @AMK Singapore 569880
 Tel : 64585441 Fax : 64553470

Vehicle No : SBS6544J
 Model No : Mercedes
 Citaro

Accident date : 03 Feb 2023
 Registered owner : Go Ahead Singapore Pte Ltd
 Date of Estimate : 08/03/23
 My Ref : BF-IC-1120

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Parts Changed (3 days)

- 1) Exit Door Glass Panel P/N: P/N : 6286749006
- 2) Labour and material cost for removal and assembly

Total Charge

S\$1600 *ent ✓ 10% - 1440*
 S\$300 *100*

Subtotal

S\$ 1900 *1540*

Parts Repair

- 1) Repair NSR Corner Bumper
- 2) Repair NS Engine Door Panel
- 3) Repair NS Last 2 Body Panels Scratched
- 4) Painting of all repaired parts

S\$600 *450*
 S\$850 *650 1100*

1540
1100

2640

BOXFRESH PTE LTD
 WORKSHOP: 154 GUL CIRCLE SINGAPORE 629611
 OFFICE: 7030 ANG MO KIO AVE 5 #06-49 NORTHSTAR SINGAPORE 569880
 T: +65 64585441 • F: +65 64553470 • E: business@boxfresh.com.sg • W: www.boxfresh.com.sg

Tanjin 92495749
up 2/5/23
p/p Resurvey new parts
Tanjin @ (the answer)
2 days