

Celine Fong (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Tuesday, 20 June 2023 2:33 PM
To: Taufikh (LKKAUTO); Xin Yu (LKK Auto); SUR; Carrine Leong; jiajee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: FINAL REVISION - SND9364D- OD AIG - SURVEYED 2 MAR 23
Attachments: PA02262023 - SND 9364 D - AUDI A3 SPORTBACK 1.5 TFS - FRONT - AIG (OD).xlsx; WhatsApp Image 2023-04-20 at 10.32.17 AM.jpeg; WhatsApp Image 2023-04-20 at 10.32.16 AM (1).jpeg; WhatsApp Image 2023-04-20 at 10.32.15 AM.jpeg; WhatsApp Image 2023-04-20 at 10.32.16 AM.jpeg

Hi Taufikh and all,

Revised estimate and photos attached.

Pls confirm repair cost of \$12,139.52 @ 5 days.

Your early closure is appreciated.

Best regards - Johnny Boo

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0226/2023/EQ
DATE : 1-Mar-23
WIP : 10238

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/3/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Taufikh

5 days - ok - John

20-Jun-23

OWNER'S NAME : MR KONDRATOV RUSLAN
ADDRESS : 36 KEPPEL BAY DRIVE
#04-80
SINGAPORE 098653
TELEPHONE : HP +65 82432134
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220012622-01
VEHICLE NO : **SND 9364 D**
MODEL CODE : AUDI A3 SPORTBACK 1.5 TFS
MODEL YEAR : 10/2/2022
ENGINE NO : DFY 309709
CHASSIS NO : WAUZZZGY1NA026361
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Feb-23
PLACE OF ACCIDENT : ALONG EXPRESSWAY AYE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SND 9364 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$	350.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. TO REPAIR LHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,500.00	\$	1,000.00
4	TO RESPRAY FRONT BUMPER, BONNET AND LHS FRONT FENDER.	\$	3,000.00	\$	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 6,522.00	\$	3,122.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 9364 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,778.00	\$ 1,422.40
2	FRONT BUMPER FIXING PARTS	1	\$ 307.00	
3	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 137.00	
4	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$ 458.00	\$ 366.40
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 281.00	
6	FRONT BUMPER AIR GUIDE- LH	1	\$ 71.00	
7	FRONT BUMPER TRIM COVER - LH	1	\$ 110.00	\$ 87.60
8	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 181.00	
9	FRONT PARKING AID SENSOR SUPPORT - LH	1	\$ 46.00	
10	RADIATOR GRILLE	1	\$ 1,167.00	\$ 933.60
11	RADIATOR GRILLE CLOSING ELEMENT - CENTER	1	\$ 223.00	
12	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 793.00	
13	FRONT BUMPER FOAM FILLER PIECE	1	\$ 127.00	
14	FRONT BUMPER GUIDE SECTION - LH	1	\$ 57.00	
15	FRONT BUMPER TOP COVER	1	\$ 94.00	
16	CAUTION SIGN STICKER	1	\$ 17.00	
17	AIR CONDITONER STICKER	1	\$ 9.00	
18	HORN LOW TONE - LH	1	\$ 157.00	
19	HORN BRACKET	2	\$ 54.00	
20	HORN BRACKET - LH	2	\$ 75.00	
SUB TOTAL SPARE PARTS		:	\$ 6,142.00	\$ 2,810.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 9364 D

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		c/f	\$		
21	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 572.00		
22	FRONT PARKING AID SEAL RING	4	\$ 54.00		
23	BONNET	1	\$ 3,330.00	\$	2,664.00
24	BONNET IMPACT PROTECTION	1	\$ 32.00	\$	25.12
25	BONNET STRIKER - LH	1	\$ 130.00		
26	BONNET LOCK	1	\$ 241.00		
27	BONNET RELEASE ELEMENT	1	\$ 69.00		
28	BONNET BOWDEN CABLE - CENTER	1	\$ 66.00		
29	BONNET RELEASE CABLE COVER	1	\$ 12.00		
30	HEADLIGHT - LH	1	\$ 4,323.00	\$	3,458.40
31	HEADLIGHT HOSE - LH	1	\$ 29.00		
32	LIFT CYLINDER - LH	1	\$ 223.00		
33	LIFT CYLINDER HOSE	1	\$ 112.00		
34	FRONT WHEEL HOUSING LINER - LH	1	\$ 198.00		
35	FRONT WHEEL HOUSING LINER CLOSING ELEMENT - LH	1	\$ 24.00		
36	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 22.00		
37	RADIATOR AIR GUIDE - LH / RH	2	\$ 90.00		
38	RADIATOR AIR GUIDE - LOWER CENTRE	1	\$ 61.00		
39	RADIATOR AIR GUIDE SEAL - RH	1	\$ 15.00		
40	FRONT NUMBER PLATE	S/N	\$ 60.00	\$	60.00
41	SUNDRIES		\$ 400.00		
TOTAL SPARE PARTS		:	\$ 16,205.00	\$	9,017.52
TOTAL LABOUR CHARGES		:	\$ 6,522.00	\$	3,122.00
GRAND TOTAL		:	\$ 22,727.00	\$	12,139.52

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

bi-30/05/23