

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Nadaraja, Deeban

Date: 03 Mar 2023

**Preliminary Advice**

Vehicle No	: SND9364D	Accident Date	: 28/02/2023
Make	: AUDI A3	Policy No.	: 7220012622-01
Assignment Date	: 03/03/2023	Excess	: S\$0.00
Date of Inspection	: 02/03/2023	Est. Duration of Repair	: 5
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,727.00
Revised Amount	:S\$	14,402.00
Check Items (Estimated)	:S\$	3,577.00
Total	:S\$	17,979.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	154,000.00
COE / PARF Rebate	:S\$	88,752.00
Salvage Value	:S\$	
Margin for Repair	:S\$	65,248.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Part by Part repair.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.