

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0226/2023/EQ
DATE : 1-Mar-23
WIP : 10238

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/3/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR KONDRATOV RUSLAN
ADDRESS : 36 KEPPEL BAY DRIVE
#04-80
SINGAPORE 098653
TELEPHONE : HP +65 82432134
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220012622-01
VEHICLE NO : **SND 9364 D**
MODEL CODE : AUDI A3 SPORTBACK 1.5 TFS
MODEL YEAR : 10/2/2022
ENGINE NO : DFY 309709
CHASSIS NO : WAUZZZGY1NA026361
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Feb-23
PLACE OF ACCIDENT : ALONG EXPRESSWAY AYE


ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNO 9364 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. S/N	\$ 480.00 ✓	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE. S/N	\$ 350.00 ✓	
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. TO REPAIR LHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. ✓ ✓	\$ 2,500.00	1000
4	TO RESPRAY FRONT BUMPER, BONNET AND LHS FRONT FENDER. ✓ X	\$ 3,000.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK. S/N	\$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 6,522.00	


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 9364 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,778.00	de
2	FRONT BUMPER FIXING PARTS	1	\$ 307.00	X
3	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 137.00	?
4	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$ 458.00	ana
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 281.00	?
6	FRONT BUMPER AIR GUIDE- LH	1	\$ 71.00	?
7	FRONT BUMPER TRIM COVER - LH	1	\$ 110.00	de
8	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 181.00	X
9	FRONT PARKING AID SENSOR SUPPORT - LH	1	\$ 46.00	?
10	RADIATOR GRILLE	1	\$ 1,167.00	ana
11	RADIATOR GRILLE CLOSING ELEMENT - CENTER	1	\$ 223.00	?
12	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 793.00	?
13	FRONT BUMPER FOAM FILLER PIECE	1	\$ 127.00	?
14	FRONT BUMPER GUIDE SECTION - LH	1	\$ 57.00	?
15	FRONT BUMPER TOP COVER	1	\$ 94.00	?
16	CAUTION SIGN STICKER	1	\$ 17.00	?
17	AIR CONDITONER STICKER	1	\$ 9.00	?
18	HORN LOW TONE - LH	1	\$ 157.00	X
19	HORN BRACKET	2	\$ 54.00	X
20	HORN BRACKET - LH	2	\$ 75.00	X
SUB TOTAL SPARE PARTS		:	\$ 6,142.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 9364 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 572.00	?
22	FRONT PARKING AID SEAL RING	4	\$ 54.00	bt ✓
23	BONNET	1	\$ 3,330.00	bt ✓
24	BONNET IMPACT PROTECTION	1	\$ 32.00	X
25	BONNET STRIKER - LH	1	\$ 130.00	X
26	BONNET LOCK	1	\$ 241.00	X
27	BONNET RELEASE ELEMENT	1	\$ 69.00	X
28	BONNET BOWDEN CABLE - CENTER	1	\$ 66.00	X
29	BONNET RELEASE CABLE COVER	1	\$ 12.00	X
30	HEADLIGHT - LH	1	\$ 4,323.00	cut ✓
31	HEADLIGHT HOSE - LH	1	\$ 29.00	?
32	LIFT CYLINDER - LH	1	\$ 223.00	?
33	LIFT CYLINDER HOSE	1	\$ 112.00	?
34	FRONT WHEEL HOUSING LINER - LH	1	\$ 198.00	X
35	FRONT WHEEL HOUSING LINER CLOSING ELEMENT - LH	1	\$ 24.00	X
36	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 22.00	?
37	RADIATOR AIR GUIDE - LH / RH	2	\$ 90.00	?
38	RADIATOR AIR GUIDE - LOWER CENTRE	1	\$ 61.00	?
39	RADIATOR AIR GUIDE SEAL - RH	1	\$ 15.00	?
40	FRONT NUMBER PLATE	S/N	\$ 60.00	bt ✓
41	SUNDRIES		\$ 400.00	?
TOTAL SPARE PARTS			\$ 16,205.00	
TOTAL LABOUR CHARGES			\$ 6,522.00	
GRAND TOTAL			\$ 22,727.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Taughlin 97495749
Not Authorise
Ex: 1b9
resurvey before paint
5 days
Taughlin 1111 and 1111

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT