



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23002299/Awy3e2 Date: 17/05/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBL 2285U	Veh. Inspected	SKM 3104R	
Policy No.		Coverage (\$)	0.00	
Claim No.	IVS23/0448	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	03/03/2023	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ CLA200	c.c	1595	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	WDD1173432N061842	Colour	WHITE	
Odometer	120031 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	DUNLOP	6 mm	
L/H Front Tyre	225/40 R18	DUNLOP	6 mm	
R/H Rear Tyre	225/40 R18	DUNLOP	6 mm	
L/H Rear Tyre	225/40 R18	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/02/2023	Inspection Date	03/03/2023	
Survey held at	SOON SAN MOTOR TRADING BLK 3006 UBI ROAD 1 #01-390 SINGAPORE 408716			
5a. Remarks				
A)REGISTRATION DATE: 19 FEB 2014 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	