



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0235/2023/EQ
DATE : 3-Mar-23
WIP : 10151

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 3/3/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR MOHAMMAD BIN KAMSAN
ADDRESS : 11 TAMPINES STREET 86
#15-31
SINGAPORE 528588
TELEPHONE : HP +65 98582835
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : -
VEHICLE NO : **SNB 7229 K**
MODEL CODE : AUDI A3 SEDAN 1.5 TFSI
MODEL YEAR : 9/9/2021
ENGINE NO : DFY 292713
CHASSIS NO : WAUZZZGY3NA006743
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Feb-23
PLACE OF ACCIDENT : COLLYER QUAY



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 7229 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	✓ ✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	X
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR ASSY.	S/N \$	280.00	✓ ✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	1000 ✓
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR AND LHS WING MIRROR COVER.	\$	4,000.00	1200 ✓
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	✓ ✓
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓ ✓
TOTAL LABOUR CHARGES		:	\$ 7,682.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 7229 K

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$ 1,778.00	✓ 1422.40
2	FRONT BUMPER FIXING PARTS <i>Neu</i>	1	\$ 307.00	x
3	FRONT BUMPER CLOSING ELEMENT - LH <i>Neu</i>	1	\$ 137.00	x
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Neu</i>	1	\$ 281.00	x
5	FRONT BUMPER AIR GUIDE - LH <i>Dented</i>	1	\$ 71.00	✓ 56.16
6	FRONT BUMPER TRIM COVER - LH <i>Neu</i>	1	\$ 110.00	x
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Neu</i>	1	\$ 181.00	x
8	FRONT PARKING AID SENSOR SUPPORT - LH <i>Not Neu</i>	1	\$ 46.00	? x
9	FRONT BUMPER GUIDE SECTION - LH <i>Dented</i>	1	\$ 57.00	✓ 45.60
10	FRONT BUMPER TOP COVER <i>2</i>	1	\$ 94.00	x
11	CAUTION SIGN STICKER	1	\$ 17.00	x
12	AIR CONDITIONER STICKER	1	\$ 9.00	x
13	HORN LOW TONE - LH <i>Neu</i>	1	\$ 157.00	x
14	HORN BRACKET <i>Neu</i>	2	\$ 54.00	x
15	HORN BRACKET - LH	2	\$ 75.00	x
16	FRONT PARKING AID SENSOR - LH <i>Neu</i>	1	\$ 272.00	x
17	FRONT PARKING AID SENSOR - OUTER <i>Not Neu</i>	1	\$ 286.00	? x
18	FRONT PARKING AID SEAL RING <i>Not Neu</i>	4	\$ 54.00	? x
19	FRONT BUMPER WIRING SET <i>Neu</i>	1	\$ 254.00	x
20	FRONT FENDER - LH <i>Dented</i>	1	\$ 1,313.00	✓ 1050.40
SUB TOTAL SPARE PARTS		:	\$ 5,553.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 7229 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER RIVET <i>New</i>	3	\$ 12.00	<i>9.60</i>
22	FRONT FENDER CLOSING ELEMENT - LH <i>New</i>	1	\$ 34.00	<i>x</i>
23	FRONT FENDER BRACKET - LH	1	\$ 49.00	<i>? x</i>
24	FRONT FENDER BRACKET - LH	1	\$ 38.00	<i>? x</i>
25	FRONT FENDER BRACKET - LH	1	\$ 34.00	<i>? x</i>
26	FRONT FENDER BRACE - LH	1	\$ 104.00	<i>? x</i>
27	FRONT FENDER ATTACHMENT PARTS <i>New</i>	1	\$ 127.00	<i>x</i>
28	FRONT WHEEL HOUSING LINER - LH <i>2hd</i>	1	\$ 198.00	<i>158</i>
29	FRONT WHEEL HOUSING LINER CLOSING ELEMENT - LH <i>New</i>	1	\$ 24.00	<i>x</i>
30	HEADLIGHT - LH	1	\$ 4,323.00	<i>x</i>
31	HEADLIGHT HOSE - LH	1	\$ 29.00	<i>x</i>
32	LIFT CYLINDER - LH	1	\$ 223.00	<i>x</i>
33	LIFT CYLINDER HOSE	1	\$ 112.00	<i>x</i>
34	FRONT EXTERIOR WING MIRROR MOUNTING - LH <i>lt</i>	1	\$ 928.00	<i>742</i>
35	LHS FRONT RIM <i>lt</i>	S/N	TBC	<i>788.00</i> 730.00
36	SUNDRIES <i>2hd New</i>		\$ 500.00	<i>? x</i>
TOTAL SPARE PARTS		:	\$ 12,288.00	
TOTAL LABOUR CHARGES		:	\$ 7,682.00	
GRAND TOTAL		:	\$ 19,970.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adnan bin .
SURVEYED DATE : @3/03/23
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 05 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT