



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914			Ref: CS/AWA23002304/Uvy3e2	Date: 19/04/2023
			Code: AWA	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GX 875H	Veh. Inspected	SJL 5698Y	
Policy No.	BVFCB0014112300	Coverage (\$)	0.00	
Claim No.	NSV2300062/HLF	Excess (\$)	0.00	
Assign From	CHAN PEGGY	Assign Date	03/03/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	MR053BK4107035569	Colour	SILVER	
Odometer	270841 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	CONTINENTAL	6 mm	
L/H Front Tyre	215/55 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	215/55 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	215/55 R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/02/2023	Inspection Date	27/03/2023	
Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	