

(08/11/13) waf

ASS - REC. BY: Amu

REF:

CS/LPC 2300 2306/Ray3

0393

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: GBG 81Eat Workshop m/s Woon Menhof 50, Bukit Saruk ST 23 #01-06Insured: LPC2

Policy No.

Claims No.

Sum Insured: Excess: 500

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 75K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT - 60K

Veh No:

GBG 81EYr Regn: 2018 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Pick-upMake: TOYOTA HILUX D/CAB PICK-UP 2ND C.C 2393Colour: GREEN

A/C: Insured / Std / NI / NA

Sp. Reading: 127 968

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MROCBBDD 400501316

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 265/65R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FIRENZA

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 20/02/23D.O.I. 06/03/23

Survey held at

Woon MenhDes. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

28, Gul Drive, Singapore 629476 Tel : 63531131

(Email Address : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

OD CLAIM

To : Lonpac Insurance Bhd
Motor Claims Dept

Date : 03 Mar 2023

Dear Sirs :

Fax : 6896 8706

RE : ESTIMATE COST FOR TOYOTA HILUX 2.4 - GBG81E
ALONG KJE (NEAR YEW TEE FLYOVER ON 20/02/2023

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Front bumper <i>de</i>	1pc	\$ 300.00
2	Front bumper retainer @\$ <i>m</i>	2pcs	Check item
3	Front bumper lower grille <i>de</i>	1pc	\$ 100.00
4	Front bumper reinforcement <i>bf</i>	2pcs	Check item
5	Horn <i>cm</i>	1pc	Check item
6	Front center grille <i>cm</i>	1pc	Check item
7	Front center chrome <i>cm</i>	1pc	\$ 480.00
8	Emblem <i>cm</i>	1pc	Check item
9	Front support panel <i>repair</i>	1pc	Check item
10	Bace panel <i>bf</i>	1pc	Check item
11	Radiator side garnish <i>de</i>	1pc	Check item
12	Clips @\$ <i>m</i>	1pc	Check item
13	Under engine cover <i>de</i>	1pc	Check item
14	Support top garnish <i>de</i>	1pc	Check item
15	Front headlamp @\$360ea <i>cm</i>	2pcs	\$ 720.00
16	Front fender lh <i>X</i>	1pc	Check item
17	Front radiator <i>X</i>	1pc	Check item
18	Air con condensor <i>X</i>	1pc	Check item
Sum Carried Forward			\$ 1,600.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 1,600.00

Sum Carried Forward

19	Fan cowling X	1pc	Check item
20	Fan blade X	1pc	Check item
21	Fan motor X	1pc	Check item
22	Front bonnet bt/	1pc	\$ 820.00
23	Front bonnet hinge @\$ bt/	2pcs	Check item
24	Front bonnet lock X	1pc	Check item
25	Front bonnet inner trim X	1pc	Check item
26	Front bonnet top chorme cm/	1pc	\$ 120.00
			\$ 2,540.00
Add 15%			\$ 1,881.00
			\$ 4,421.00

27	Coolant X		\$ 35.00
28	Front number plate bt/	1pc	\$ 35.00

Labour Charge & Misc

To remove, repair, replace & install front
damaged parts.

}
}

\$ 1,000.00

To R & R air con system
To refill & top up air con gas

}
}

\$ 150.00 X

To R & R front radiator

Resue

4p 90010068

\$ 120.00 X

To R & R wiring

5 days

\$ 60.00 30

To putty & spray painting.

P/P

\$ 1,000.00

Total

06/03/23 P1505

\$ 6,821.00

EXCESS: 500

Revert

Resue before paint

All prices quoted are subjected to GST.

This is a computer generated document. No signature is required.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Business
Owner ID:	039J
Vehicle No.:	GBG81E
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Mar 2023
Vehicle Make:	TOYOTA
Vehicle Model:	HILUX DOUBLE CAB TURBO PICKUP 2WD MT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	2GDC364756
Chassis No.:	MROCB8DD400501316
Maximum Power Output:	-
Open Market Value:	\$29,511.00
Original Registration Date:	03 Jul 2018
First Registration Date:	03 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$33,316.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	02 Jul 2028
COE Category:	C - Goods Vehicle & Bus
COE Period (Years):	10
PQP Paid:	\$26,579.00
COE Rebate Amount:	\$14,138.00
Total Rebate Amount:	\$14,138.00

The information contained herein is correct as at 07 Mar 2023

OK