

ASS. REF. BY: Tan JH

REF:

CS/SPC 23002308 / Tay

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 420K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJX542H Yr Regn: 2010, May

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Avante C.C. 1591

Colour: Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 367183 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM H04415M 144020280

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Long Long

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 7/3/23

Survey held at Lee Hong & Co.

Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt, Frt O/S, U/C, Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Unit 912K

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / I.B.R. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

____ S + RS. ____ SI

Photos

Others

TOTAL

LEE HONG & CO MOTOR SERVICE

Blk 9 Sin Ming Road
#01-36 Sin Ming Industrial Estate
Singapore 575644.

T. (65) 6458 8460
F. (65) 6455 5379
E. leehong36@rocketmail.com

Date	21-Feb-2023	Ref.:	TP Claim
------	-------------	-------	----------

Owner Particulars			
Name	TOH WEI QUAN		
# Nos	SXXXX070G	Mobile No.	98758222
Address	BLK109, ALJUNIED CRESCENT		
	#08-72		
	SINGAPORE 38909		

Vehicle Particulars	
Number	SJX542H
Model	HYUNDAI AVANTE 1.6 AUTO ABS AIRBAG 2WD 4DR
Engine	G4FCAU848878
Chassis	KMH DU41BMAU020290
Year	12-May-10

Accident Details	
Date	20 February, 2023
Time	00.30HRS
Place	PAYA LEBAR RD TOWARDS GEYLANG

Insured With	
Insurance	NTUC Income Insurance Co-operative Ltd
Policy No.	5103177907-04
Expiry	

Driver Particulars			
Name	As above		
Nric Nos.		Mobile No.	
Address			

COMMENTS	COMPANY STAMP
1. This Estimate is based on visual Inspections of visible damages on the above vehicle.	
2. We will keep you informed if further damages are found.	
3. This Estimate is valid for 30 days only.	
	Signature

	Estimate Cost Of Repairs	Vehicle #	SJX542H
--	---------------------------------	------------------	----------------

QTY	DESCRIPTIONS	UNITS	AMOUNTS
1 pce	Front bumper fascia		\$ de 452.20
1 pce	Front bumper reinforcement		\$? 253.30
1 pce	Front bumper sponge		\$? 101.30
2 pcs	Front bumper retainers <i>LHx</i>	\$ 13.40	\$ RHde 26.80
1 pce	Front bumper lower grille		\$ tn 185.30
1 pce	Front bumper o/s cover <i>dust cover.</i>		\$ de 121.30
1 pce	Front lower spoiler		\$ tn 285.00
1 pce	O/s headlamp assy <i>X2</i>		\$ Brd 359.50
1 pce	O/s front shock absorber		\$? 327.00
1 pce	O/s front shock absorber top mounting		\$? 54.70
1 pce	O/s front wheel bearing		\$? 152.20
1 pce	O/s front knuckle arm		\$? 347.10
1 pce	O/s front lower arm		\$? 356.40
1 pce	O/s front drive shaft		\$ x 945.80
1 pce	Front stabilizer bar		\$ x 268.70
1 pce	Front stabilizer bar n/s linkage		\$ x 77.30
1 pce	Steering rack and pinion assy		\$ x 1,906.20
1 pce	Front lower splash cover		\$ de 132.10
1 pce	Front sub-frame assy		\$ bt 2,250.00
2 pcs	Engine mountings	\$ 287.00	\$? 574.00
1 pce	Transmission box mounting		\$? 236.00
1 pce	O/s front fender		\$ Rx 352.90
1 pce	O/s front fender inner plastic shield		\$ de 37.60
1 pce	O/s front door		\$ bt 847.10
2 pcs	O/s front door hinges	\$ 41.00	\$ X 82.00
1 pce	O/s front door rubber		\$ ng 89.00
1 pce	O/s front door mirror assy		\$ dis 375.00
1 pce	O/s side sill panel		\$ Rx 511.00
1 pce	Rear bumper fascia		\$ de 431.80
2 pcs	Rear bumper side retainers <i>RHx</i>	\$ 30.70	\$ LHde 61.40
1 pce	Fuel tank cover		\$ bt 67.10
1 pce	N/s rear fender		\$ bt 1,216.60
1 pce	N/s rear fender inner trim cover		\$ X 189.30
1 pce	N/s rear fender inner shield		\$? 95.60
1 pce	N/s rear lamp assy		\$? 374.50
1 pce	Rear windscreen inner lower rubber beading		\$ ng 37.10
1 pce	N/s rear shock absober assy		\$? 275.00
1 pce	N/s rear top arm		\$? 175.20
1 pce	N/s rear lower arm		\$? 268.60
1 pce	N/s rear knuckle arm		\$? 353.20
1 pce	N/s rear wheel bearing		\$? 332.70

