



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SKJ4578R Toyota Vois

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper	\$ 850.00 BRC \$641.20
2	2	Front bumper retainer	\$ 180.00 CR \$45.10
3	1	Front light support bracket -left (L)	\$? 125.00 DNG ✓ XNS
4	1	Front light support bracket -left R	\$? 125.00 DNG ✓ XNS
5	1	Front middle chrome	\$ 280.00 CLK \$193.70 } 286
6	1	Front middle chrome silving lining	\$ 150.00 CRC ✓
7	1	Front lower grille	\$ 220.00 CRC \$140
8	1	Number palte holder	\$ 100.00 BT \$50
9	1	Foglamp -left	\$ 250.00 CRC X NN
10	1	Foglamp cover-left	\$ 180.00 CRC ✓ 103
11	1	Foglamp -right	\$ 250.00 x
12	1	Foglamp cover-right	\$ 180.00 x
13	1	Reinforcement	\$ 480.00 DT \$380
14	2	Reinforcement 2 support	\$ 360.00 DT ✓ XR
15	1	Front support panel -top	\$ 550.00 R
16	1	Front lower support -lower	\$ 380.00 R
17	2	Front panel side holder bracket	\$ 300.00 DNG ✓ XR
18	2	Air duct trim cover	\$ 240.00 DNG ✓ \$120/pc
19	1	Front bumper guide trim	\$ 220.00 DNG ✓ \$140
20	1	Condenser	\$ 950.00 DT ✓ old damaged
21	1	Toyota Logo	\$ 95.00 NEC \$75
22	1	Horn	\$ 125.00 x
23	2	Bonnet hinge	\$ 200.00 DT \$29.6 X NN
		Sub-total parts	\$ 6,790.00

\$2,229.9

25% = 557.475

\$1672.425



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SKJ4578R Toyota Vois

No	Qty	Parts Description	Estimated Parts Price
		<u>Special Nett Items</u>	
1	6	Front bumper lower grille clips	\$ 60.00 \$30
2	8	Front bonnet inner board clips	\$ 80.00 \$30 X NN
3	10	Front lower chrome clips	\$ 100.00 \$30 X NN
4	8	Front support panel top garnish clips	\$ 80.00 \$30
5	10	Front middle chrome clips	\$ 60.00 \$30 X NN
6	1	Number plate and casing	\$ 80.00 \$40
7	1	Gas and coolant	\$ 100.00 \$50 X NN
		Special Nett Total	\$ 560.00 \$100



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SKJ4578R Toyota Vois

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,600.00 \$800 600
2	To putty and spray painting front portion.	\$ 1,500.00 \$200 \$600
3	To apply anti rust proofing to front left affected area	\$ 120.00 \$50
4	To check wiring and focus front headlamp.	\$ 80.00 \$70
5	To remove and install front left undercarriage parts.	\$ 350.00 x
6	To balance front right wheel.	\$ 80.00 x
7	To conduct wheel alignment.	\$ 120.00 x
8	To check front horn and focus and function	\$ 80.00 x
9	Remove and replace condenser, check leaking top up coolant/gas	\$ 150.00 \$50 X
10	To check aircon related parts leaking	\$ 120.00 x
11	To remove and check radiator /water system realted leaking	\$ 120.00 x
Total labour :		\$ 4,420.00
		\$ 1480

05 days

Akid

071031023

1630hrs

Total parts and labour

\$3252.425

~ \$3.3k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: