



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF23002310/Kqy3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1		Date:	05/07/2023
HEMMANT ROADSINGAPORE 438675			
ATTN: HAFIZUL FARHAN		Code:	SPF
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	QX 481S	Veh. Inspected	SMF 8026M
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2023/013	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	03/03/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTDZS3EU00J034643	Colour	METALLIC BLACK
Odometer	269604 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	205/60R16	DUNLOP	3 mm
L/H Front Tyre	205/60R16	DUNLOP	3 mm
R/H Rear Tyre	205/60R16	FIRENZA	8 mm
L/H Rear Tyre	205/60R16	FIRENZA	8 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	01/03/2023	Inspection Date	06/03/2023
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 Sector C SINGAPORE 575643.		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	