



ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : TPVehicle No. : YP2294AMake & Model : HINO XZU710RYear of Manufacture : 2015Chassis No. : JHHUCS3H80K016082Ins Company : ALLIANZ INSURANCEEngine No. : Excess : Policy No. : Date of Accident : 23.12.2022Time of Accident : 1300Suggested Days of Repair : In-house Vehicle Assessor**Repair Estimates**Case Owner : Signature : Parts (a) Cost / List Price Items \$ 1,864.20Plus/Less 15% \$ 279.63Total of Cost / List \$ 2,143.83(b) Nett Price Items \$ -Less Total of Nett Item (c) Special Nett Items Total Parts Cost (Appendix A) \$ 2,143.83Labour (Appendix B) \$ 700.00Total Repair Cost \$ 2,843.83

Contact No

**Frt Counter Operation**

63837103 - Patrick Tia

[PatrickTia@sparkcarcare.com](mailto:PatrickTia@sparkcarcare.com)

63837730 - Brenda Ng

[BrendaNg@sparkcarcare.com](mailto:BrendaNg@sparkcarcare.com)

63837466 - Rohani

[RohaniM@sparkcarcare.com](mailto:RohaniM@sparkcarcare.com)**Workshop Operation**

63837656 - Ngo Toh Wee

[Ngotw@sparkcarcare.com](mailto:Ngotw@sparkcarcare.com)

63838115 -

63837362 -

*NOT AUTHORIZED*  
*Murray Bepain*

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Hennoth  
 Company : CLC  
 Survey conducted on : 6/3/23 at 9.50am

**Remarks By Surveyor**(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.(b) Recommended Days of Repair : 02 day(s)(c) Resurvey : Required / ~~Not Required~~(d) Excess : \$ (e) Signature of surveyor : Le Date: 6/3/23

# Spark Car Care

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road S (579701)  
Tel: 63837168 / 63837466 Fax: 62815767

## Spare Parts

Vehicle No : YP2294A Case Owner : JOHARI  
Make & Model : HINO XZU710R Year Manufacture : \_\_\_\_\_  
Chassis No : JHHUCS3H80K016082 Engine No : \_\_\_\_\_  
Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_  
Order By : \_\_\_\_\_ Type of Claim : TP

S/No		QTY	Cost Price	List Price	Nett Price	S/N	Disposit Surveyo
1	REAR BUMPER	1	<i>B</i>	\$ 1,389.70		✓	
2	RHR TAIL LAMP ASSEMBLY	1	<i>CM</i>	\$ 352.30		✓	
3	RHR TAIL LAMP PANEL	1	<i>R</i>	\$ 122.20		X	
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							
31							
32							
33							
34							
35							
36							
37							
38							
39							
40							
41							
42							
43							
44							
45							
46							
47							
48							
49							
50							

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

If any of the quoted parts are recommended to be repaired, then an additional labour charge is charged accordingly under supplementary.

**ComfortDelGro Engineering Pte Ltd**  
205 Braddell Road S (579701)  
Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No. : YP2294A  
Make & Model : HINO XZU710R

Case Owner	:	<u>JOHARI</u>
Year of Manufacture	:	<u>2015</u>

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*