



ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : TPVehicle No. : YP2294AMake & Model : HINO XZU710RYear of Manufacture : 2015Chassis No. : JHHUCS3H80K016082Ins Company : ALLIANZ INSURANCEEngine No. : Excess : Policy No. : Date of Accident : 23.12.2022Time of Accident : 1300Suggested Days of Repair : In-house Vehicle Assessor : **Repair Estimates**Case Owner : Signature : **Parts (a) Cost / List Price Items** \$ 1,864.20Plus/Less 15% \$ 279.63Total of Cost / List \$ 2,143.83(b) Nett Price Items \$ -Less Total of Nett Item (c) Special Nett Items **Total Parts Cost (Appendix A)** \$ 2,143.83**Labour (Appendix B)** \$ 700.00**Total Repair Cost** \$ 2,843.83

Contact No

**Frt Counter Operation**

63837103 - Patrick Tia

[PatrickTia@sparkcarcare.com](mailto:PatrickTia@sparkcarcare.com)

63837730 - Brenda Ng

[BrendaNg@sparkcarcare.com](mailto:BrendaNg@sparkcarcare.com)

63837466 - Rohani

[RohaniM@sparkcarcare.com](mailto:RohaniM@sparkcarcare.com)**Workshop Operation**

63837656 - Ngo Toh Wee

[Ngotw@sparkcarcare.com](mailto:Ngotw@sparkcarcare.com)

63838115 -

63837362 -

*The above total will be subjected to 7% G.S.T.*Name of Surveyor : Company : Survey conducted on :  at **Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair :  day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ (e) Signature of surveyor :  Date:

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62815767

## Spare Parts

Vehicle No : YP2294A

Case Owner : JOHARI

Make & Model : HINO XZU710R

Year Manufacture : \_\_\_\_\_

Chassis No : JHHUCS3H80K016082

Engine No : \_\_\_\_\_

Sales Order : \_\_\_\_\_

Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_

Type of Claim : TP

S/No		QTY	Cost Price	List Price	Nett Price	S/N	Disposit Surveyo
1	REAR BUMPER	1		\$ 1,389.70			
2	RHR TAIL LAMP ASSEMBLY	1		\$ 352.30			
3	RHR TAIL LAMP PANEL	1		\$ 122.20			
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62815767

Case Owner	:	<u>JOHARI</u>
Year of Manufacture	:	<u>2015</u>

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*