



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKQ7L

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No 63236
Reg No/Reg Date SKQ7L / 04/08/2020
Date In/Mileage / 0
Chassis No W1K2906892A0324057
Engine No 17798060142525
Make/Model MB/T 63 S 4MATIC+
Colour/Trim 021 197 Obsidian Bl/ 045 501 Designo Nap

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WA000001	Credit	02/03/2023/ 14:28	CH	371 / Go Chee Han				
Description of Goods / Services								
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : M0027640 // 23-2-2023								
DRIVE IN/TP VEH NUMBER : 24-2-2023 // SNH8059X - ALLIANZ								
DATE IN/DATE SURVEY:								
DIRECT SETTLEMENT BY:								
A BPILAB								
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.								
A BPIRES								
RESpray FRONT BUMPER								
A BPILAB								
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO								
IDENTIFICATION STANDARD. NETT								
A BPILAB								
TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT					1.00	2918.36	00.00	2918.36
M FRONT AMG BUMPER					1.00	134.01	00.00	134.01
M LH/FRONT BUMPER LOWER TRIM STRIP					1.00	134.01	00.00	134.01
M RH/FRONT BUMPER LOWER TRIM STRIP					1.00	194.01	00.00	194.01
M CTR/FRONT BUMPER LOWER TRIM STRIP					1.00	86.17	00.00	86.17
M TOWING EYE COVER					1.00	184.09	00.00	184.09
M LH/UPPER FRONT BUMPER BRACKET					1.00	184.71	00.00	184.71
M RH/UPPER FRONT BUMPER BRACKET					1.00	278.33	00.00	278.33
M FRONT BUMPER TOP BASIC CARRIER					1.00	169.64	00.00	169.64
M FRONT BUMPER TOP INNER BASIC CARRIER					8.00	3.52	00.00	28.16
M SPRING NUT					1.00	345.55	00.00	345.55
M MOUNTING CONSOLE					1.00	100.21	00.00	100.21
M RH/HEADLAMP BOTTOM BRACKET					1.00	7167.64	00.00	7167.64
M RH/HEADLAMP UNIT					20.00	5.34	00.00	106.80
M RIVET FOR BUMPER								

THIS IS NOT AN OFFICIAL TAX INVOICE

Handwritten notes: 4 days, 10/03/23 @ 1030, Res before paint

Handwritten calculations: 960 1920.00, 800 960.00, 480.00, 120.00

Go Chee Han
DID: 6771 4336 HP: 9181 7717
Email: cheehan.go@cyclecarrage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be sent to and approved by the repairer
- Authorized signatory and company stamp is subject to final approval from Insurance Company

Nett 15,511.69
8% GST on 15511.69 1240.94
Total Payable 16,752.63

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs include GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg

