

SAS-KIV

LKK-

INSURANCE: CHINA TAIPING

MVA: LIM T S

VEHICLE NO.: **SH 6673B**

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taufiq 97495749
 WP' 3/1/22 @ 430pm
 L/S Resmay after repair
 Taufiq @ khando.com
 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 03.01.2023 12:08

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5579266

JC NO.305541301

OMER COMFORT TRANSPORTATION PTE LTD 7010045 OMER NO 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (P)	REGN NO: SH 6673B	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL I-40	DATE/TIME IN 31.12.2022 18:15
	YR OF MANU. 28.07.2016	TARGET DATE
	CHASSIS CODE KMHLB41UMGU091358	COMPLETION DATE/TIME:


UNT CARD NO.

JOB DESCRIPTION

Accident Date: 31.12.2022
 NATURE: 3P 31.12.2022

NO LABOR CODE
 00010 PB

DESCRIPTION
 LUMPSUM REPAIR-SH 6673B-TP



KEYED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Adgement Slip

Exit Pass

Vehicle No.: SH 6673B LIMITS

Vehicle No.: SH 6673B

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard