

SAS-KIV

LKK-

INSURANCE: CHINA TAIPING

MVA: L I M T S

VEHICLE NO.: SH 6673B

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

617

Усп, 3/1/22 в 430pm

L/S Resumy after repair

tanpura @ khant.com

2 days

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 03.01.2023 12:08

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5579266

JC NO.305541301


OMER	REGN NO: SH 6673B	MILEAGE
3 COMFORT TRANSPORTATION PTE LTD	MAKE: HYUNDAI	FUEL
OMER NO 7010045	MODEL I-40	E.....1/2.....F
ESS 383 SIN MING DRIVE	YR OF MANU. 28.07.2016	DATE/TIME IN 31.12.2022 18:15
Singapore SINGAPORE 575717	CHASSIS CODE KMHLB41UMGU091358	TARGET DATE
(R) 65508755 (O)		COMPLETION DATE/TIME:
(P)		
UNT CARD NO.		

JOB DESCRIPTION

Accident Date: 31.12.2022
ATURE: 3P 31.12.2022

'NO LABOR CODE
00010 PB

DESCRIPTION
LUMPSUM REPAIR-SH 6673B-TP



KEYED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Io.: SH 6673B LIMITS

Vehicle No.: SH 6673B

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard