

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E**02 MAR 2023**

Estimate No. : b1 65183 Page No. : 1 of 4
Date Estimated : 02/03/2023
Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -
UNITED POWER ENTERPRISE PTE LTD
2 Yishun Industrial Street 1
#07-01, Northpoint Bizhub
Singapore 768159

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJR368B	WBA8A16080NU75957	23/08/2017	320iA/4Dr	128167

DESCRIPTION	VALUE
To replace rear bumper and attachments.	1,275.00
To painting rear bumper.	1,038.00
To check electrical wiring system and lighting at the rear section for proper function.	177.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	177.00
Sundries.	80.00

Total Labour 1: **2,747.00**

DESCRIPTION	QTY	PRIC	VALUE
INSERT FOR BUMPER REAR (M)	1	148.00	148.00
REAR BUMPER PANEL PRIMED (M)	1	1,331.85	1,331.85
SET MOUNTS PDC SENSOR RR (M)	1	71.60	71.60
(DG/SL) ADHESIVE SET K6	1	53.05	53.05
Total Parts :			1,604.50

Labour 1	:	2,747.00
Parts	:	1,604.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 8%	:	348.12
Grand Total	:	4,699.62



** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **