

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO	: AIG	DATE	: 3-Mar-23
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SNG944Z		
MODEL	: TOYOTA NOAH		
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 3-Mar-23
		TIME	: 0900HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 2,080.50	\$ 2,080.50
2	TAILGATE LOGO <i>New</i>	1	\$ 85.00	\$ 85.00
3	TAILGATE EMBLEM "HYBRID SYNERGY DRIVE" <i>New</i>	1	\$ 82.50	\$ 82.50
4	TAILGATE HINGE <i>3 set</i>	2	\$ 130.00	\$ 260.00
5	TAIL GATE DAMPER <i>1 set</i>	2	\$ 230.00	\$ 460.00
6	TAILGATE LOCK <i>Dented</i>	1	\$ 480.00	\$ 480.00
7	TAIL GATE LOCK CATCH <i>New</i>	1	\$ 90.00	\$ 90.00
8	TAILGATE INNER BOARD TRIM <i>cracked</i>	1	\$ 766.20	\$ 766.20
9	TAILGATE WEATHERSTRIP <i>the new</i>	1	\$ 330.00	\$ 330.00
10	TAILGATE INNER HANDLE <i>New</i>	1	\$ 90.00	\$ 90.00
11	REAR WINDSCREEN MOULDING <i>New</i>	1	\$ 190.00	\$ 190.00
12	TAILGATE ALTERNATIVE <i>cracked</i>	1	\$ 210.00	\$ 210.00
13	TAILGATE BUZZEL <i>cracked</i>	1	\$ 150.30	\$ 150.30
14	REAR BUMPER <i>Dented</i>	1	\$ 822.30	\$ 822.30
15	REAR BUMPER SIDE RETAINER <i>New</i>	2	\$ 62.40	\$ 124.80
16	REAR BUMPER TOWING COVER <i>New</i>	1	\$ 98.20	\$ 98.20
17	REAR END PANEL <i>Dented</i>	1	\$ 666.50	\$ 666.50
18	REAR END PANEL TOP GARNISH <i>New</i>	1	\$ 288.90	\$ 288.90

TOTAL PRICE \$ 7,275.20

4803.30
3602.47

LESS 25% \$ 1,818.80

SUB TOTAL PRICE \$ 5,456.40

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>He m</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
2	TAILAGTE INNER BOARD CLIPS(SET) <i>Ne</i>	1	\$ 20.00	\$ 20.00 <i>-</i>
3	TAILAGTE WINDSCREEN SEALANT <i>Ne</i>	1	\$ 100.00	\$ 100.00 <i>60</i>
4	REAR BUMPER CLIP (SET) <i>Ne</i>	1	\$ 20.00	\$ 20.00 <i>-</i>
5	REAR END PANEL GARNISH CLIP (SET) <i>Ne m</i>	1	\$ 20.00	\$ 20.00 <i>+</i>
6	REAR END PANEL SEALANT <i>Ne</i>	1	\$ 150.00	\$ 150.00 <i>60</i>
7	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00 <i>20</i>

360

TOTAL \$ 580.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,400.00	<i>800</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	<i>800</i>	
3	TUFF COAT	\$ 250.00	<i>60</i>	
4	WIRING CHECK	\$ 120.00	<i>30</i>	
5	TO CONDUCT WATER LEAKAGE TEST	\$ 100.00	<i>X</i>	
6	TO TRANSFER TAIL GATE MECHNISM	\$ 180.00	<i>60</i>	
7	LABOUR TO REMOVE AND REFIT WINDSCREEN	\$ 120.00	<i>/</i>	
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>	
9	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>50</i>	

1970

TOTAL

\$3,730.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,036.40
TOTAL LABOUR COST : \$ 3,730.00
TOTAL REPAIR COST : \$ 9,766.40

APPROVED DETAILS

Adrian Cj
2/5 06/03/23.
06 Days
total: 5932.47
4/5: 4.7K