



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2303950

300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV Date 20/06/2023  
Reference CC4/LPC23002329/Upa3q2  
Code LPC2

### PROFESSIONAL SERVICE FEE

Vehicle No. SLF 8289H  
Insured Veh. SFR 2202E  
Claim No. 23/23/23/VP05/027057  
Policy No. Z23VP05032676  
Accident Date 02/03/2023  
Inspection Date 07/03/2023

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (8%)</b>                | <b>32.00</b>  |
| <b>Grand Total</b>             | <b>432.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                                            |                 |                                                               |  |
|-------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------|--|
| LONPAC INSURANCE BHD<br>300 BEACH ROAD<br>#17-04/07 THE CONCOURSE SINGAPORE 199555                                                        |                                                                                            |                 | Ref: CC4/LPC23002329/Upa3q2<br>Date: 20/06/2023<br>Code: LPC2 |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                                            |                 |                                                               |  |
| Insured Veh.                                                                                                                              | SFR 2202E                                                                                  | Veh. Inspected  | SLF 8289H                                                     |  |
| Policy No.                                                                                                                                | Z23VP05032676                                                                              | Coverage (\$)   | 0.00                                                          |  |
| Claim No.                                                                                                                                 | 23/23/23/VP05/027057                                                                       | Excess (\$)     | 0.00                                                          |  |
| Assign From                                                                                                                               | GERALD                                                                                     | Assign Date     | 03/03/2023                                                    |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                                            |                 |                                                               |  |
| Make & Model                                                                                                                              | HONDA VEZEL (A)                                                                            | c.c             | 1496                                                          |  |
| Engine No.                                                                                                                                | HIDDEN                                                                                     | Year of Reg.    | 2016                                                          |  |
| Chassis No.                                                                                                                               | RU11203966                                                                                 | Colour          | BLACK                                                         |  |
| Odometer                                                                                                                                  | 204514 KM                                                                                  | Steering        | IN ORDER                                                      |  |
| Brakes                                                                                                                                    | IN ORDER                                                                                   | Modification    | SPORTS RIM                                                    |  |
| General                                                                                                                                   | GOOD                                                                                       |                 |                                                               |  |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                                            |                 |                                                               |  |
|                                                                                                                                           | Size                                                                                       | Make            | Balance                                                       |  |
| R/H Front Tyre                                                                                                                            | 225/50 R17                                                                                 | BRIDGESTONE     | 6 mm                                                          |  |
| L/H Front Tyre                                                                                                                            | 225/50 R17                                                                                 | BRIDGESTONE     | 6 mm                                                          |  |
| R/H Rear Tyre                                                                                                                             | 225/50 R17                                                                                 | BRIDGESTONE     | 6 mm                                                          |  |
| L/H Rear Tyre                                                                                                                             | 225/50 R17                                                                                 | BRIDGESTONE     | 6 mm                                                          |  |
| <b>4. Description of Damages</b>                                                                                                          |                                                                                            |                 |                                                               |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br><br>DAMAGES SEE DETAILS.                                                            |                                                                                            |                 |                                                               |  |
| <b>5. General Information</b>                                                                                                             |                                                                                            |                 |                                                               |  |
| Accident Date                                                                                                                             | 02/03/2023                                                                                 | Inspection Date | 07/03/2023                                                    |  |
| Survey held at                                                                                                                            | T K LEE AUTOMOTIVE PTE LTD<br>NO. 1 KAKI BUKIT AVE 6<br>#02-47 AUTOBAY<br>SINGAPORE 417883 |                 |                                                               |  |
| <b>5a. Remarks</b>                                                                                                                        |                                                                                            |                 |                                                               |  |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                            |                 |                                                               |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                        |                                                                                            |                 |                                                               |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                       |                                                                                            |                 | 6 Working Days                                                |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 8289H

| Qty | Description of Parts                    | Condition                                           | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------------------|-----------------------------------------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>      |                                                     |                           |                   |
| 1   | TAILGATE                                | BADLY DENTED                                        | 1,287.10                  | 1,099.20          |
| 1   | SET TAILGATE GLASS MOULDING             | NECESSARY                                           | 121.20                    | 121.20            |
| 1   | TAILGATE EMBLEM 'VEZEL'                 | NECESSARY                                           | 58.60                     | 58.60             |
| 2   | TAILGATE LAMPS -R/L @\$470.30           | N/S NOT<br>NECESSARY / O/S<br>SCRATCHED/<br>CRACKED | 940.60                    | 340.80            |
| 1   | TAILGATE INNER LOCK                     | BENT                                                | 280.90                    | 180.20            |
| 1   | TAILGATE INNER PULL POCKET              | TWISTED                                             | 89.90                     | 89.90             |
| 1   | TAILGATE INNER TRIM BOARD               | DEFORMED /<br>CRACKED                               | 486.90                    | 486.90            |
| 1   | TAILGATE W/STRIP                        | TWISTED                                             | 198.10                    | 198.10            |
| 2   | TAILGATE DAMPER -R/L @\$141.60          | NOT NECESSARY                                       | 283.20                    | -                 |
| 2   | TAILGATE STOPPER @\$12.60               | NOT NECESSARY                                       | 25.20                     | -                 |
| 2   | TAILLAMPS -R/L @\$528.10                | N/S NOT<br>NECESSARY / O/S<br>CRACKED               | 1,056.20                  | 528.10            |
| 1   | REAR BUMPER                             | DENTED                                              | 891.60                    | 545.00            |
| 2   | REAR BUMPER REFLECTOR -R/L @\$171.20    | N/S NOT<br>NECESSARY / O/S<br>CRACKED               | 342.40                    | 171.20            |
| 2   | REAR BUMPER SIDE -R/L @\$241.60         | N/S TO REPAIR<br>SEE LABOUR / O/S<br>DEFORMED       | 483.20                    | 241.60            |
| 2   | REAR BUMPER SIDE RETAINER -R/L @\$48.60 | NOT NECESSARY                                       | 97.20                     | -                 |
| 1   | REAR END PANEL                          | DENTED / BENT                                       | 759.10                    | 517.30            |
| 1   | REAR END PANEL GARNISH                  | TWISTED                                             | 241.20                    | 160.80            |
| 1   | REAR FLOOR BOARD                        | TORN                                                | 370.60                    | 370.60            |
| 1   | REAR FLOOR SPONGE TRAY                  | TORN                                                | 361.80                    | 361.80            |
| 1   | REAR FLOOR PANEL                        | TO REPAIR SEE<br>LABOUR                             | 781.60                    | -                 |
| 1   | REAR FLOOR UNDERCOVER                   | NOT NECESSARY                                       | 281.90                    | -                 |
| 2   | REAR FENDER TRIM BOARD-R/L @\$586.60    | N/S NOT<br>NECESSARY / O/S<br>TWISTED               | 1,173.20                  | 366.00            |

Report Ref No. CC4/LPC23002329/Upa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty                | Description of Parts                                                                                                          | Condition                    | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--------------------|-------------------------------------------------------------------------------------------------------------------------------|------------------------------|---------------------------|-------------------|
| 2                  | REAR FENDER PROTECTOR -R/L @\$341.20                                                                                          | N/S NOT NECESSARY / O/S TORN | 682.40                    | 199.00            |
| 1                  | REAR SMART KEYLESS ANTENNA                                                                                                    | NOT NECESSARY                | 191.20                    | -                 |
| 1                  | REAR SMART KEYLESS BUZZLE                                                                                                     | NOT NECESSARY                | 196.80                    | -                 |
|                    | LESS 20% DISCOUNT                                                                                                             |                              | -2,336.42                 | -1,207.26         |
|                    |                                                                                                                               |                              | 9,345.68                  | 4,829.04          |
|                    | <b><u>SPECIAL NETT ITEMS</u></b>                                                                                              |                              |                           |                   |
| 1                  | SET TAILGATE GLASS SEALANT (SN)                                                                                               | NECESSARY                    | 80.00                     | 40.00             |
| 1                  | SET TAILGATE GLASS FOAM TAPE (SN)                                                                                             | NECESSARY                    | 65.00                     | 40.00             |
| 1                  | SET TAILGATE OUTER GARNISH CLIP (SN)                                                                                          | NOT NECESSARY                | 80.00                     | -                 |
| 1                  | SET REAR BUMPER CLIP (SN)                                                                                                     | NECESSARY                    | 45.00                     | 45.00             |
| 1                  | SET REAR REVERSE SENSOR (SN)                                                                                                  | SHORTED                      | 280.00                    | 200.00            |
| 1                  | REAR REVERSE CAMERA (SN)                                                                                                      | NOT NECESSARY                | 450.00                    | -                 |
|                    |                                                                                                                               |                              | 1,000.00                  | 325.00            |
|                    | <b><u>LABOUR</u></b>                                                                                                          |                              |                           |                   |
|                    | TO REMOVE & REPLACE TAILGATE GLASS .                                                                                          |                              | 180.00                    | 120.00            |
|                    | TO TRANSFER AND REINSTALL TAILGATE COMPONENTS TO NEW TAIL.                                                                    |                              | 150.00                    | 60.00             |
|                    | TO CHECK REAR ELECTRICAL WIRING.                                                                                              |                              | 50.00                     | 20.00             |
|                    | TO REMOVE ,REPLACE REVERSE SENSOR AND CAMERA.                                                                                 |                              | 80.00                     | 50.00             |
|                    | TO REMOVE & REPLACE EXHAUST SYSTEM.                                                                                           | NOT NECESSARY                | 80.00                     | -                 |
|                    | TO TUFF KOTE.                                                                                                                 |                              | 100.00                    | 60.00             |
|                    | TO PUTTY ,SPRAY PAINT & POLISH AFFECTED PARTS .                                                                               |                              | 1,080.00                  | 800.00            |
|                    | TO PANEL BEAT ,CUT ,WELD ,REMOVE & REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER SIDE LH AND REAR FLOOR PANEL. |                              | 1,200.00                  | 880.00            |
|                    |                                                                                                                               |                              | 2,920.00                  | 1,990.00          |
| <b>GRAND TOTAL</b> |                                                                                                                               |                              | <b>13,265.68</b>          | <b>7,144.04</b>   |

Report Ref No. CC4/LPC23002329/Upa3q2



|                                                                                 |  |  |                 |
|---------------------------------------------------------------------------------|--|--|-----------------|
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS<br/>(TO ITS PRE-ACCIDENT CONDITION)</b> |  |  | <b>5,700.00</b> |
|---------------------------------------------------------------------------------|--|--|-----------------|

Report Ref No. CC4/LPC23002329/Upa3q2

**CHUA KANG SENG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SLF 8289H

### INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 8289H

RE-INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SLF 8289H

### RE-INSPECTION

