

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

Email: Sales@Leebrothers.com.sg

not Authd
her
7/3/23
4/5 & 5-700
6 days

Vehicle Number: SLF8289H

Vehicle Model: HONDA VEZEL

PAGE 1

PARTICULAR

AMOUNT

QTY

SS

LIST PRICE

1	1	TAILGATE	Body 70	1099.20	\$	1,287.10	✓
2	1	(SET) TAILGATE GLASS MOULDING	her		\$	121.20	✓
3	1	TAILGATE EMBLEM 'VEZEL'	her		\$	58.60	✓
4	2	TAILGATE LAMPS -R/L @\$470.3	Alsan o/s scrlene	340.80	\$	940.60	1pc
5	1	TAILGATE INNER LOCK	but	180.20	\$	280.90	✓
6	1	TAILGATE INNER PULL POCKET	twl		\$	89.90	✓
7	1	TAILGATE INNER TRIM BOARD	de/cru		\$	486.90	✓
8	1	TAILGATE W/STRIP	twl		\$	198.10	✓
9	2	TAILGATE DAMPER -R/L @\$141.60	11		\$	283.20	X
10	2	TAILGATE STOPPER @\$12.60	11		\$	25.20	X
11	2	TAILLAMPS -R/L @\$528.10	Alsan o/s scrlene		\$	1,056.20	1pc
12	1	REAR BUMPER	70	545	\$	891.60	✓
13	2	REAR BUMPER REFLECTOR -R/L @\$171.20	Alsan o/s scrlene		\$	342.40	1pc
14	2	REAR BUMPER SIDE -R/L @\$241.60	Als R o/s de		\$	483.20	1pc
15	2	REAR BUMPER SIDE RETAINERS -R/L @\$ 48.60	11		\$	97.20	X
16	1	REAR END PANEL	70/304	517.30	\$	759.10	✓
17	1	REAR END PANEL GARNISH	twl	160.80	\$	241.20	✓
18	1	REAR FLOOR BOARD	Torn		\$	370.60	✓
19	1	REAR FLOOR SPONGE TRAY	Torn		\$	361.80	✓
20	1	REAR FLOOR PANEL	R		\$	781.60	X
21	1	REAR FLOOR UNDERCOVER	11		\$	281.90	X
22	2	REAR FENDER TRIM BOARDS -R/L @\$586.60	Alsan o/s twl 366		\$	1,173.20	1pc
23	2	REAR FENDER PROTECTOR -R/L @\$341.20	Alsan o/s Torn 199		\$	682.40	1pc
24	1	REAR SMART KEYLESS ANTENNA	11		\$	191.20	X
25	1	REAR SMART KEYLESS BUZZLE	11		\$	196.80	X
					\$	11,682.10	
					LESS 20%	\$	2,336.42
						\$	9,345.68

LEE BROTHERS AUTOMOTIVE PTE. LTD.

Vehicle Number: SLF8289H

Vehicle Model: HONDA VEZEL

PAGE 2

PARTICULAR		AMOUNT
QTY		S\$
<u>SPECIAL NETT ITEMS</u>		
1	(SET) TAILGATE GLASS SEALANT <i>nee</i>	\$ 80.00 <i>40</i>
1	(SET) TAILGATE GLASS FOAM TAPE <i>nee</i>	\$ 65.00 <i>40</i>
1	(SET) TAILGATE OUTER GARNISH CLIP <i>11</i>	\$ 80.00 <i>X</i>
1	(SET) REAR BUMPER CLIP <i>nee</i>	\$ 45.00 <i>✓</i>
1	(SET) REAR REVERSE SENSOR <i>stuff 11</i>	\$ 280.00 <i>200</i>
1	REAR REVERSE CAMERA	\$ 450.00 <i>X</i>
		<u>\$ 1,000.00</u>

LABOUR CHARGES

TO REMOVE & REPLACE TAILGATE GLASS	\$ 180.00 <i>120</i>
TO TRANSFER AND REINSTALL TAILGATE COMPONENTS TO NEW TAIL	\$ 150.00 <i>60</i>
TO CHECK REAR ELECTRICAL WIRING	\$ 50.00 <i>20</i>
TO REMOVE, REPLACE REVERSE SENSOR AND CAMERA	\$ 80.00 <i>50</i>
TO REMOVE & REPLACE EXHAUST SYSTEM	\$ <i>11</i> 80.00 <i>X</i>
TO TUFF KOTE	\$ 100.00 <i>60</i>
TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	\$ 1,080.00 <i>800</i>
TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	\$ 1,200.00 <i>880</i>
	<u>\$ 2,920.00</u>

ESTIMATE PARTS AND LABOUR GRAND TOTAL :

\$ 13,265.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-6036.2
202
4828.04
325
(990)