

Woon Meng Motor Pte Ltd (Co.Reg.No:200603678M)

50 Bukit Batok Street 23,, #01-06 Midview Building

Singapore 659578

Tel: 6316 1131 Fax: 6316 7050 Email: woonmeng@singnet.com.sg

INSURER: **ERGO Insurance Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCG22009749	Date of Loss:	01/03/2023
Vehicle Reg. No.:	GBL9192H	Driveable?	
Driver Age/Info:	34 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	ST CONNECTIONS PTE LTD		
Driver:	WOON SOON HUAT		

Make/Model:	NISSAN NV350 CARAVAN, 2.0 DX (A)	Vehicle Reg. Date:	14/07/2022
Vehicle Colour:	GREY		
Engine No:	QR20020201R	Chassis No:	VR2E26136597
Odometer:	11625 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12		

Present Location: WOON MENG MOTOR PTE LTD (BUKIT BATOK)

COST OF CLAIMS

	Amount
Parts	5,519.80
Miscellaneous Items	0.00
Labour	1,540.00
Paintwork Labour	1,000.00
Towing	0.00

Gross Total (S\$)	8,059.80
+ GST 8.00% (S\$)	644.78
Nett Amount (S\$)	8,704.58

This claim is handled by: **HENG SEW SOW**

PAIR DETAILS

Reference

Part Source: (Last Synchronised: 03 Mar 2023)

Parts: N/A NISSAN NV350 CARAVAN 2.0 DX (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Woon Meng Motor Pte Ltd/GBL9192H/03/03/2023 18:08

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER <i>de</i>	0.00	0.00	*400.00 F
2	2		*FRONT BUMPER RETAINER <i>2cm</i>	0.00	0.00	*180.00 F
3	1		*TOWING COVER <i>X</i>	0.00	0.00	*20.00 F
4	1		*FRONT BUMPER FOG LAMP COVER LH <i>cm</i>	0.00	0.00	*80.00 F
5	1		*FRONT BUMPER REINFORCEMENT <i>X</i>	0.00	0.00	*350.00 F
6	1		*FRONT CENTER GRILLE <i>X</i>	0.00	0.00	*350.00 F
7	1		*EMBLEM <i>X</i>	0.00	0.00	*50.00 F
8	<i>2/1</i>		*FRONT HEADLAMP LH <i>cm</i>	0.00	0.00	*570.00 F
9	10		*FRONT CENTER GRILLE CLIPS <i>X</i>	0.00	0.00	*25.00 F
10	1		*FRONT PANEL <i>bt</i>	0.00	0.00	*595.00 F
11	1		*FRONT CORNER PANEL LH <i>bt</i>	0.00	0.00	*210.00 F
12	1		*FRONT CORNER SIDE SEAL LH <i>cm</i>	0.00	0.00	*23.00 F
13	1		*FRONT CORNER SIDE MIRROR LH <i>cm</i>	0.00	0.00	*115.00 F
14	1		*FRONT DOOR LH <i>cm</i>	0.00	0.00	*600.00 F
15	2		*FRONT DOOR HINGE <i>?</i>	0.00	0.00	*110.00 F
16	1		*FRONT DOOR LOCK LH <i>?</i>	0.00	0.00	*155.00 F
17	1		*FRONT STEP PANEL LH <i>cm</i>	0.00	0.00	-
18	1		*FRONT DOOR RUBBER LH <i>cm</i>	0.00	0.00	*95.00 F
19	1		*FRONT DOOR INNER TRIM LH <i>?</i>	0.00	0.00	*340.00 F
20	1		*REAR PILLAR LH <i>repair</i>	0.00	0.00	*750.00 F

F=Franchise part.

Sub Total (\$\$)	5,018.00
+ Margin on L,N Items 10.00% (\$\$)	501.80
Total Parts (\$\$)	5,519.80

Woon Meng Motor Pte Ltd/GBL9192H/03/03/2023 18:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Supplementary
gear box oil cooler in
spd - gear box hose. cut

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items1 1 ROV STICKER *na*

Sub Total (S\$)

0.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1 TO PUTTY & SPRAY PAINTING.

New

800~~1,000.00~~Labour Items2 TOWING FEE *? receipt*

New

?~~160.00~~

3 TO REMOVE, REPLACE, REPAIR & INSTALL FRONT DAMAGED PARTS

New

1000~~1,200.00~~

4 TO REMOVE & INSTALL DOOR MECHANISM AND CHECK FOR FUNCTION

New

60~~120.00~~

5 TO R & R WIRING

New

30~~60.00~~

Gross Labour Cost (S\$)

2,540.00

Woon Meng Motor Pte Ltd/GBL9192H/03/03/2023 18:08. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Rece**Up 900 10068**8 days**P/P**06/03/23 @ 1520**EXCESS: TDA**Revised**Resy before paint*