

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 4641Y

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|---------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR TAILGATE | BENT | 2,162.70 | 2,162.70 |
| 1 | REAR TAILGATE TOYOTA LOGO | NECESSARY | 65.10 | 65.10 |
| 1 | REAR TAILGATE TOYOTA HIACE STICKER | NECESSARY | 71.10 | 71.10 |
| 1 | REAR TAILGATE INNER BOARD | SERVICEABLE | 408.10 | - |
| 1 | REAR WINDSCREEN | SHATTERED | 1,458.50 | 1,191.00 |
| 1 | REAR BOOT WEATHERSTRIP | SERVICEABLE | 299.10 | - |
| 1 | REAR BUMPER | SERVICEABLE | 517.10 | - |
| 1 | REAR LAMP LH | SERVICEABLE | 303.10 | - |
| | LESS 25% DISCOUNT | | -1,321.20 | -872.48 |
| | | | 3,963.60 | 2,617.42 |
| | SPECIAL NETT ITEMS | | | |
| 1 | SET REAR BUMPER CLIPS (SN) | NOT NECESSARY | 45.00 | - |
| 1 | SET REVERSE SENSOR (SN) | SERVICEABLE | 250.00 | - |
| 1 | WINDSCREEN SEALANT (SN) | NECESSARY | 50.00 | 40.00 |
| 1 | 70KM/H STICKER (SN) | NECESSARY | 20.00 | 15.00 |
| | | | 365.00 | 55.00 |
| | <u>LABOUR</u> | | | |
| | TO REMOVE & REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS. | | 80.00 | 15.00 |
| | TO REMOVE, REINSTALL REAR WINDSCREEN. | | 200.00 | 120.00 |
| | TO REMOVE, TRANSFER TAIL GATE COMPONENTS. | | 100.00 | 60.00 |
| | TO REMOVE, REPAIR & REPLACE DAMAGED BODYPARTS, REALIGN BODYWORK AND WHERE CONSISTENT TO THE ACCIDENT. | | 600.00 | 200.00 |
| | PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS. | | 600.00 | 400.00 |
| | TO REMOVE & RENEW REVERSE SENSOR. | NOT NECESSARY | 100.00 | - |
| | RUST PROOFING ON AFFECTED PORTIONS. | | 80.00 | 30.00 |
| | | | 1,760.00 | 825.00 |
| | GRAND TOTAL | | 6,088.60 | 3,497.42 |

Report Ref No. CS/LIP23002335/Kny3e2



Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS | 2,800.00 |
|--------------------------------------|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | |

Report Ref No. CS/LIP23002335/Kny3e2

MARKET VALUE: \$66,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$13,479.00=NETT VALUE: \$52,521.00

KONG SENG CHEONG

Licensed Appraiser