



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23002335/Kny3e2 Date: 21/03/2023 Code: LIP	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YQ 1259D	Veh. Inspected	GBJ 4641Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	IVS23/0462	Excess (\$)	0.00	
Assign From	TED SEAH	Assign Date	06/03/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HIACE (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTFHT02P500248787	Colour	WHITE	
Odometer	136924 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	TRIANGLE	9 mm	
L/H Front Tyre	195 R15X8	TRIANGLE	9 mm	
R/H Rear Tyre	195 R15X8	GOFORM	8 mm	
L/H Rear Tyre	195 R15X8	GOFORM	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION AND REAR WINDSCREEN SHATTERED. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	27/02/2023	Inspection Date	07/03/2023	
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		