



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept			S1000005 / ICFIC1		Mr Lin Jiawei 523C Tampines Central 7 #11-101 Tampines Greenleaf Singapore 523523 Mobile: 91275571		
			Document No. 0				
			Document Date 03/03/2023				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	MXUA80R	ANXGB E1	15/09/2021	SNB7845G	0	22400	67/TP/SNB7845G
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTEAC3BH90J000214		M20A0438584	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES TP CLAIM TP-YP9385A ACC DATE:03/03/2023 DRIVE IN:03/03/2023 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30.00	
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION				366.36	
3	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM				198.00	
4	B	BP-MECH2 TO CONDUCT ADJUSTMENT ON FRT WAVE RADAR SENSOR				198.00	
5	S	BP-SUBLET REPLACE SPORT RIM AND CONDUCT WHEEL BALA NCING				99.00	
6	B	BP-MECH2 CONDUCT FULL WHEEL ALIGNMENT				198.00	
7	B	BP-MECH2 REPLACE FRT LH SUSPENSION SYSTEM				792.00	
8	Z	BP-SLANT SUPPLY SEALANT (NETT)-LH FRT DOOR				80.00	
9	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW DOO R				396.00	
10	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 17 UBI ROAD 4
 SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept			S1000005 / ICFIC1		Mr Lin Jiawei 523C Tampines Central 7 #11-101 Tampines Greenleaf Singapore 523523 Mobile: 91275571		
			Document No. 0				
			Document Date 03/03/2023				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	MXUA80R	ANXGB E1	15/09/2021	SNB7845G	0	22400	67/TP/SNB7845G
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTEAC3BH90J000214		M20A0438584	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
11	B	BP-LAB2 REPLACE LH ACCIDENT DAMAGED PARTS				3960.00	
		STRAIGHTEN & ALIGN LH ACCIDENT AFFECTED AREA					
12	B	BP-RES2 RESPRAY JOB ON LH ACCIDENT AFFECTED AREA				3936.00	
		S					
13	1	T52119-4D977 COVER, FR BUMPER	1.00	751.30		751.30	
14	2	T53395-48110 SEAL, HOOD TO FR END	1.00	112.40		112.40	
15	3	T52536-48080 RETAINER, FR BUMPER	1.00	120.70		120.70	
16	4	T52134-48090 BRACKET, FR BUMPER,	1.00	192.70		192.70	
17	5	T90467-07215 CLIP	8.00	3.00		24.00	
18	6	T52411-48070 GUARD, FR BUMPER	1.00	706.80		706.80	
19	7	T53802-48160 FENDER SUB-ASSY, FR	1.00	1510.80		1510.80	
20	8	T53876-48190 LINER, FR FENDER, LH	1.00	296.00		296.00	
21	9	L90467-07220 CLIP	10.00	3.00		30.00	
22	0	T53883-48060 SEAL, FR FENDER, LH	1.00	34.20		34.20	
23	1	T53828-48060 PROTECTOR, FR FENDER	1.00	110.20		110.20	
24	2	T81185-48J10 UNIT, HEADLAMP	1.00	7847.70		7847.70	
25	3	T67002-48191 PANEL SUB-ASSY, FR	1.00	2115.70		2115.70	
26	4	T75922-48070 TAPE, BLACK OUT,	1.00	13.20		13.20	
27	5	T75986-48080 STRIPE, FR DOOR,	1.00	52.30		52.30	
28	6	T75966-48020 STRIPE, FR DOOR	1.00	31.40		31.40	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts		Less
					Labour		
					Sublet		Amount Due
					Lubrication/Fluid		
					Others		

Customer Copy



Borneo Motors

inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept	S1000005 / ICFIC1	Mr Lin Jiawei 523C Tampines Central 7 #11-101 Tampines Greenleaf Singapore 523523 Mobile: 91275571
	Document No. 0	
	Document Date 03/03/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	MXUA80R	ANXGB E1	15/09/2021	SNB7845G	0	22400	67/TP/SNB7845G

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEAC3BH90J000214	M20A0438584	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
29	7	T67862-48130 WEATHERSTRIP, FR	1.00	259.30		259.30
30	8	T68610-48100 CHECK ASSY, FR DOOR	1.00	265.50		265.50
31	9	T68720-12151 HINGE ASSY, FR DOOR,	1.00	117.20		117.20
32	0	T68740-12120 HINGE ASSY, FR DOOR,	1.00	133.20		133.20
33	1	L69040-30A80 LOCK ASSY, FR DOOR	1.00	675.00		675.00
34	2	T67004-48260 PANEL SUB-ASSY, RR	1.00	1974.20		1974.20
35	3	T76902-48010 MUDGUARD SUB-ASSY,	1.00	59.60		59.60
36	4	T75074-48010 MOULDING SUB-ASSY,	1.00	415.80		415.80
37	5	T75078-48020 MOULDING SUB-ASSY,	1.00	287.60		287.60
38	6	T75860-48060 MOULDING ASSY, BODY	1.00	578.00		578.00
39	7	T42611-48B50 WHEEL, DISC	1.00	2782.20		2782.20
40	8	T48520-80635 ABSORBER ASSY,	1.00	567.80		567.80
41	9	T48069-42070 ARM SUB-ASSY,	1.00	954.20		954.20
42	0	T43330-49225 JOINT ASSY, LWR BALL	1.00	286.30		286.30
43	1	T43212-33130 KNUCKLE, STEERING,	1.00	883.30		883.30
44	2	T43550-33070 HUB & BEARING ASSY,	1.00	733.70		733.70
45	3	T61020-48010 MEMBER ASSY, SIDE,	1.00	458.10		458.10

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total 35,831.76
	Please acknowledge receipt of vehicle	Parts 25,380.40 Labour 9,986.00 Sublet 465.36 Lubrication/Fluid 0.00 Others 0.00	GST 8.00% 2,866.54
			Less 0.00 Amount Due 38,698.30

Customer Copy