4/17/23, 11:22 AM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI23002346/UQP3Q2

17/04/2023 Date:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMPCSNW00217102202

**Claimant Vehicle** 

SLU9756R

Insured Vehicle No:

SJW8146X

Date of Loss:

No:

03/03/2023

Nature of

Claim:

TP

Claim SNM23D201682/C02/KHONGLH No:

Yes

144123 km

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SLU9756R** Reg No:

TOYOTA C-HR HYBRID, 1.8 S CVT (A) Make & Model: Reg. Date:

19/12/2017 (Man. Year: 2017)

Engine No: 2ZR8075961 Chassis No: ZYX102028163

Odometer:

Colour: Red

**Engine Capacity:** 1797 cc

Market Value/New Car Price: N/A Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable):

**Engine Modification:** Pre-accident Condition: Handbrake (Serviceable): Yes No

**CONDITION OF TYRES** 

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17 Rear Left Side: Front Left Side: Goodyear 7 mm Goodyear 7 mm Front Right Side: Goodyear 7 mm Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,783.10	1,511.70	1,271.40	45.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	810.00	690.00	46.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,283.10	2,321.70	1,961.40	45.79
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	4,283.10	1,800.00	2,483.10	57.97
+ GST 8.00/8.00% (S\$)	342.65	144.00	198.65	57.97
Nett Amount (S\$)	4,625.75	1,944.00	2,681.75	57.97

**INSPECTION** 

Date of Assignment: 06/03/2023

Hock Wah Motor Workshop Pte Ltd (Bedok)

Blk 3011, Bedok Industrial Park E,, #01-Date Inspected: 03/04/2023 Inspected At:

2008/2010/2012

Singapore 489977

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

### Reference

4/17/23, 11:22 AM

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Apr 2023)

Parts: M1-SUV TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLU9756R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Dented / Bent	1,426.10 FL	*1,426.10 FL
2	1		*FRONT DOOR PROTECTOR LH	Grazed	366.80 FL	*366.80 FL
3	1		*REAR DOOR PROTECTOR LH	Grazed	222.70 FL	*222.70 FL
4	1		*WING MIRROR ASSEMBLY LH (Cracked)	Not Consistent With The Impact	1,579.10 FL	*- FL
5	1		*WING MIRROR COVER LH	Not Necessary	116.10 FL	*- FL
6	1		*REAR DOOR LH (NPA)	Repair	0.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$) - List Item Discount on L Items 25.00/25.00% (S\$)				,	<b>2,015.60</b> 503.90	
				Total Parts (S\$)	2,783.10	1,511.70
			Report was unsubmitte	ed during this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	700.00	280.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	700.00	500.00
3	ANTI-RUST COATING	New	100.00	30.00
		Gross Labour Cost (S\$)	1,500.00	810.00
	Report was unsubn	nitted during this print-out.		

< END OF ESTIMATES >