

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Khong Lin Hui Lynn

Date: 10 Apr 2023

**Preliminary Advice**

|                    |                                                                                                                         |                         |              |
|--------------------|-------------------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SJW8146X                                                                                                              |                         |              |
| TP Vehicle No      | : SLU9756R                                                                                                              | Accident Date           | : 03/03/2023 |
| Make               | : TOYOTA C-HR HYBRID                                                                                                    | Assignment Date         | : 06/03/2023 |
| Date of Inspection | : 03/04/2023                                                                                                            | Est. Duration of Repair | : 3          |
| Inspection At      | : HOCK WAH MOTOR WORKSHOP PTE LTD (BEDOK)<br>BLK 3011, BEDOK INDUSTRIAL PARK E., #01-2008/2010/2012<br>SINGAPORE 489977 |                         |              |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 4,283.12 |
| Revised Amount              | :S\$ | 2,321.70 |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 2,321.70 |
|                             |      |          |
| Lump Sum Repair             | :S\$ | 1,800.00 |

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.