

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT123002346/ugp3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLU 9756R

at Workshop m/s

hockwah (can.)

of

Insured:

SJW 8146X

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

787k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

LEA 31564

Date / Time

Action / Instruction

Day 1st.

Veh No:

SLU 9756R

Yr Regn:

19/12/17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota C-HR Hybrid c.c 1797

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

14423

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

24X102028163

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

2.5/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

03/03/23

D.O.I.

3/4/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1) 10/4/23

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

)

TOTAL

Report Format :

MER-TP

Lump Sum / I.B.I. (\$

1800

8/4/23 1/5 @ 1800 in hand Any size (Red @ 2483.12, 587.7)

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 301i BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355/6243 8121
R.O.C No: 200104141D GST Reg. No. 20-0104141-D

TO: 96959059
LEO BOON SENG
BLK 765 BEDOK RESERVOIR VIEW
#07-263
SINGAPORE 470765
TEL: FAX:
PH: 96959059
ATTN:

ESTIMATE BILL

Number: EB00006228
Date: 3/3/2023
Case No: AD00013688
Vehicle No: SLU9756R
Chassis: ZYX102028163
Year of Mfr: 2017
Policy No: 5119611938-01
Model: TOYOTA C-HR
HYBRID 1.8S CVT

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	FRONT DOOR LH	1.0	1,426.10	25	1,069.58
2	FRONT DOOR PROTECTOR LH	1.0	366.80	25	275.10
3	REAR DOOR PROTECTOR LH	1.0	222.70	25	167.03
4	WING MIRROR ASSEMBLY LH	1.0	1,579.10	25	1,184.33
5	WING MIRROR COVER LH	1.0	116.10	25	87.08
List Price - Parts Sub Total					2,783.12
6	REAR DOOR LH - REPAIR	1.0			0.00
Special Nett Price - Parts Sub Total					0.00
Parts Total					2,783.12
7	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	700.00	0	700.00
8	SPRAY PAINT ON THE AFFECTED AREAS	1.0	700.00	0	700.00
9	ANTI-RUST COATING	1.0	100.00	0	100.00
Labour 1 Sub Total					1,500.00
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature:					
SINGAPORE DOLLARS : FOUR THOUSAND SIX HUNDRED TWENTY-FIVE AND CENTS SEVENTY-SEVEN ONLY			Less Excess		0.00
			SUBTOTAL		4,283.12
			GST 8.00%		342.65
			TOTAL		4,625.77

Date of accident : 03/03/2023 02:00 PM. Place : PIE > BEDOK NORTH ROAD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE