



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 1979 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 ✓	✓
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,400.00 X NM	
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00 X NM	
5	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$ 280.00 ✓	✓
6	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$ 280.00 ✓	✓
TOTAL LABOUR CHARGES		\$ 3,990.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 1979 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET, REAR BUMPER AND RHS HEADLIGHT. TO REPAIR RHS FRONT FENDER TOP SUPPORT, RHS FRONT DOOR AND RHS REAR FENDER. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S 6,500.00	1650 ✓
8	TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER, RHS FRONT FENDER TOP SUPPORT (RHS UPPER A-PILLAR), RHS FRONT DOOR, RHS REAR FENDER AND REAR BUMPER.	S 6,500.00	3000 + 550. 3550
9	TO RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N S 2,800.00	? ✓ ✓
10	TO RENEW RHS FRONT RIM WITH TYRE AND RHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N S 560.00	✓ ✓
11	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N S 384.00	✓ ✓
TOTAL LABOUR CHARGES		S 20,734.00	

Car-in

8/3/23

wip: 10276

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AG - Taufik

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 1979 K

			DAMAGED PARTS & PRICES		REMARKS
S/N	PARTS DESCRIPTION	QTY	S/NETT		
1	FRONT BUMPER	1	\$	1,778.00	de 1422.40
2	FRONT BUMPER FIXING PARTS	1	\$	307.00	X nu
3	FRONT BUMPER CLOSING ELEMENT - RH	1	\$	132.00	de 109.60
4	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$	458.00	X nu
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$	281.00	? de 224.40
6	FRONT BUMPER AIR GUIDE - RH	1	\$	71.00	? de 56.16
7	FRONT BUMPER SPOILER	1	\$	345.00	de 275.60
8	FRONT BUMPER TRIM COVER - RH	1	\$	110.00	nu 87.60
9	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$	181.00	nu 144.40
10	FRONT PARKING AID SENSOR SUPPORT - RH	1	\$	46.00	X
11	RADIATOR GRILLE	1	\$	1,162.00	X nu
12	RADIATOR GRILLE CLOSING ELEMENT - CENTER	1	\$	223.00	X
13	FRONT BUMPER REINFORCEMENT BEAM	1	\$	292.00	X
14	FRONT BUMPER FOAM FILLER PIECE	1	\$	122.00	X
15	FRONT BUMPER GUIDE SECTION - RH	1	\$	57.00	de 45.60
16	FRONT BUMPER SUPPORT - LH / RH	2	\$	22.00	X
17	FRONT BUMPER TOP COVER	1	\$	94.00	✓
18	CAUTION SIGN STICKER	1	\$	17.00	X nu
19	AIR CONDITIONER STICKER	1	\$	9.00	X
20	HORN HIGH TONE - RH	1	\$	165.00	X
SUB TOTAL SPARE PARTS			:	\$	6,388.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2373 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 1979 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN BRACKET	1-2	\$4.00 X	W - X m
22	HORN BRACKET - RH	2	\$5.00 X	} X m
23	FRONT PARKING AID SENSOR - OUTER	1	\$86.00 X	
24	FRONT PARKING AID SENSOR - RH	1	\$94.00 X	
25	FRONT PARKING AID SEAL RING	4	\$4.00 X	
26	FRONT BUMPER WIRING SET	1	\$54.00 X	
27	FRONT FENDER - RH	1	1,313.00	bi - 1050.40
28	FRONT FENDER RIVET	3	\$2.00	na - 16
29	FRONT FENDER CLOSING ELEMENT - RH	1	\$4.00 X	de - 26.88
30	FRONT FENDER BRACKET - RH	1	\$9.00	? m - 38.72
31	FRONT FENDER BRACKET - RH	1	\$8.00	? W - 29.76
32	FRONT FENDER BRACKET - RH	1	\$4.00	? W - 26.88
33	FRONT FENDER BRACE - RH	1	\$104.00	? H - 82.80
34	FRONT FENDER ATTACHMENT PARTS	1	\$127.00 X	} X m
35	FRONT FENDER CLOSING ELEMENT - RH	1	\$39.00	
36	FRONT FENDER INSULATION - RH	1	\$51.00 X	
37	FRONT WHEEL HOUSING LINER - RH	1	\$198.00	de - 158
38	FRONT WHEEL HOUSING LINE CLOSING ELEMENT - RH	1	\$24.00	} X
39	BONNET	1	\$3,330.00	Ry - X
40	BONNET ATTACHMENT PARTS	1	\$209.00 X	
SUB TOTAL SPARE PARTS		:	\$	6,639.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT:

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 1979 K

DAMAGED PARTS & PRICES				
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET IMPACT PROTECTION	1	\$ 32.00	✓
42	BONNET ENGINE SOUND ABSORBER	1	\$ 223.00	✓
43	BONNET STRIKER - RH	1	\$ 130.00	X
44	BONNET LOCK - RH	1	\$ 241.00	X
45	BONNET RELEASE ELEMENT	1	\$ 69.00	X
46	BONNET RELEASE LEVER	1	\$ 16.00	✓
47	BONNET BOWDEN CABLE - CENTER	1	\$ 66.00	✓
48	BONNET RELEASE CABLE COVER	1	\$ 12.00	✓
49	FRONT PLENUM CHAMBER COVER	1	\$ 187.00	X
50	HEADLIGHT - RH	1	\$ 4,323.00	OK
51	HEADLIGHT HOSE - RH	1	\$ 29.00	X
52	LIFT CYLINDER - RH	1	\$ 223.00	X
53	LIFT CYLINDER HOSE	1	\$ 112.00	X
54	LOCK CARRIER	1	\$ 1,030.00	X
55	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 22.00	X
56	READY-MIX COOLANT	6	\$ 325.00	X
57	RADIATOR AIR GUIDE - RH	1	\$ 45.00	X
58	RADIATOR AIR GUIDE SEAL - RH	1	\$ 15.00	X
59	RADIATOR AIR GUIDE - LOWER CENTRE	1	\$ 61.00	X
60	REAR BUMPER	1	\$ 2,026.00	Rp
SUB TOTAL SPARE PARTS		:	\$ 9,188.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT:

3458.40

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6641 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 1979 K

DAMAGED PARTS & PRICES				
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	REAR BUMPER FIXING PARTS	1	\$ 348.00 X	} X un
62	REAR BUMPER LOCKING MECHANISM - RH	1	\$ 17.00 X	
63	REAR BUMPER GUIDE SECTION - RH	1	\$ 68.00 X	
64	REAR PARKING AID SENSOR - RH	1	\$ 285.00 X	
65	REAR PARKING AID SEAL RING	1	\$ 14.00 X	
66	REAR WHEEL HOUSING LINER - RH	1	\$ 281.00 X	} del - 1215.20 bt - 667.20 ht - 144.80 un - 316.40 bt - 513.20 ht - 443.20 ht - 110 bt - 84.40 ht - 1238.40 ht - 374.80 un - 85.60 ht - 105.20
67	FRONT AND REAR ALUMINIUM RIM - RH	1	\$ 1,038.00	
68	REAR ASSEMBLY CARRIER	1	\$ 834.00 X	
69	BONDED RUBBER BUSHES	1	\$ 181.00 X	
70	REAR LOWER CONTROL ARM - RH	1	\$ 396.00 X	
71	REAR STABILIZER	1	\$ 470.00 X	
72	REAR WHEEL BEARING HOUSING - RH	1	\$ 642.00 X	
73	REAR WHEELHUB WITH BEARING	1	\$ 180.00 X	
74	REAR GUIDE JOINT - RH	1	\$ 138.00 X	
75	REAR COUPLING ROD	1	\$ 106.00 X	
76	REAR JOINTED SHAFT - RH	1	\$ 1,548.00 X	
77	REAR GAS SHOCK ABSORBER	1	\$ 469.00 X	
78	REAR STEERING GEAR WITH TRACK RODS	1	\$ 5,916.00 X	
79	REAR TRACK ROD	1	\$ 107.00 X	
80	REAR TIE ROD END - RH	1	\$ 132.00 X	
SUB TOTAL SPARE PARTS		:	\$ 14,989.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408655
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 1979 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	^{Front} REAR NOISE INSULATION	1	\$ 408.00	X ^{HA}
82	REAR WINDOW SLOT SEAL TRIM STRIP - RH OUTER	1	\$ 274.00	X ^{HA}
83	REAR WINDOW GUIDE TRIM STRIP - RH	1	\$ 314.00	X ^{HA}
84	FRONT NUMBER PLATE	S/N	\$ 60.00	X ^{HA}
85	RHS FRONT TYRE	S/N	TBC	80% 300
86	SUNDRIES		\$ 1,000.00	? 235.12 new
TOTAL SPARE PARTS		:	\$ 39,260.00	
TOTAL LABOUR CHARGES		:	\$ 20,734.00	
GRAND TOTAL		:	\$ 59,994.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0236/2023/EQ

15-Mar-23

CHANG

1 of 1

SMA 1979 K

AUDI A3 SPORTBACK 1.5 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	AERIAL FOR ACCESS	\$ 100.00	CNA X nn
GRAND TOTAL		\$ 100.00	

For Premium Automobiles Pte Ltd



Authorised Signature