

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0236/2023/EQ
DATE : 3-Mar-23
WIP : 10276

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 3/3/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Taufikh

15 days exclude 2 Sundays

Johnny Boo 15 May 23

OWNER'S NAME : MR YEO KAI KIAT KELLY
ADDRESS : BLK 525 HOUGANG AVE 6
#01-181
SINGAPORE 530525
TELEPHONE : HP +65 91881014
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220039816
VEHICLE NO : **SMA 1979 K**
MODEL CODE : AUDI A3 SPORTBACK 1.5 TFS
MODEL YEAR : 30/11/2021
ENGINE NO : DFY 302010
CHASSIS NO : WAUZZZGY4NA013698
MILEAGE : 20,473
DATE IN : 2-Mar-23
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Mar-23
PLACE OF ACCIDENT : ALONG MARINA VIEW (OUTSIDE KPMG BUILDING)
ASIA SQUARE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 1979 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$ 350.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$	1,400.00	
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$	1,200.00	
5	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$	280.00	\$ 280.00
6	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$	280.00	\$ 280.00
TOTAL LABOUR CHARGES		:	\$ 3,990.00	\$ 1,390.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 1979 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>C/F</i>		<i>\$ 1,390.00</i>
7	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET, REAR BUMPER AND RHS HEADLIGHT. TO REPAIR RHS FRONT FENDER TOP SUPPORT, RHS FRONT DOOR AND RHS REAR FENDER. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	6,500.00	<i>\$ 1,650.00</i>
8	TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER, RHS FRONT FENDER TOP SUPPORT, RHS UPPER A-PILLAR, RHS FRONT DOOR, RHS REAR FENDER AND REAR BUMPER.	\$	6,500.00	<i>\$ 3,550.00</i>
9	TO RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$	2,800.00	<i>\$ 2,800.00</i>
10	TO RENEW RHS FRONT RIM WITH TYRE AND RHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	560.00	<i>\$ 560.00</i>
11	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	<i>\$ 384.00</i>
TOTAL LABOUR CHARGES		:	\$ 20,734.00	<i>\$ 10,334.00</i>

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 1979 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 1,778.00	\$	1,422.40
2	FRONT BUMPER FIXING PARTS	1	\$ 307.00		
3	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 137.00	\$	109.60
4	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$ 458.00		
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 281.00	\$	224.40
6	FRONT BUMPER AIR GUIDE - RH	1	\$ 71.00	\$	56.16
7	FRONT BUMPER SPOILER	1	\$ 345.00	\$	275.60
8	FRONT BUMPER TRIM COVER - RH	1	\$ 110.00	\$	87.60
9	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 181.00	\$	144.40
10	FRONT PARKING AID SENSOR SUPPORT - RH	1	\$ 46.00		
11	RADIATOR GRILLE	1	\$ 1,167.00		
12	RADIATOR GRILLE CLOSING ELEMENT - CENTER	1	\$ 223.00		
13	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 793.00		
14	FRONT BUMPER FOAM FILLER PIECE	1	\$ 127.00		
15	FRONT BUMPER GUIDE SECTION - RH	1	\$ 57.00	\$	45.60
16	FRONT BUMPER SUPPORT - LH / RH	2	\$ 22.00		
17	FRONT BUMPER TOP COVER	1	\$ 94.00		
18	CAUTION SIGN STICKER	1	\$ 17.00		
19	AIR CONDITIONER STICKER	1	\$ 9.00		
20	HORN HIGH TONE - RH	1	\$ 165.00		
SUB TOTAL SPARE PARTS		:	\$ 6,388.00	\$	2,365.76

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 1979 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		C/F		\$	2,365.76
21	HORN BRACKET	2	\$ 54.00		
22	HORN BRACKET - RH	2	\$ 75.00		
23	FRONT PARKING AID SENSOR - OUTER	1	\$ 286.00		
24	FRONT PARKING AID SENSOR - RH	1	\$ 294.00		
25	FRONT PARKING AID SEAL RING	4	\$ 54.00		
26	FRONT BUMPER WIRING SET	1	\$ 254.00		
27	FRONT FENDER - RH	1	\$ 1,313.00	\$	1,050.40
28	FRONT FENDER RIVET	3	\$ 12.00	\$	16.00
29	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 34.00	\$	26.88
30	FRONT FENDER BRACKET - RH	1	\$ 49.00	\$	38.72
31	FRONT FENDER BRACKET - RH	1	\$ 38.00	\$	29.76
32	FRONT FENDER BRACKET - RH	1	\$ 34.00	\$	26.88
33	FRONT FENDER BRACE - RH	1	\$ 104.00	\$	82.80
34	FRONT FENDER ATTACHMENT PARTS	1	\$ 127.00		
35	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 39.00		
36	FRONT FENDER INSULATION - RH	1	\$ 51.00		
37	FRONT WHEEL HOUSING LINER - RH	1	\$ 198.00	\$	158.00
38	FRONT WHEEL HOUSING LINE CLOSING ELEMENT - RH	1	\$ 24.00		
39	BONNET	1	\$ 3,330.00		
40	BONNET ATTACHMENT PARTS	1	\$ 269.00		
SUB TOTAL SPARE PARTS		:	\$ 6,639.00	\$	3,795.20

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 1979 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		C/F		\$ 3,795.20
41	BONNET IMPACT PROTECTION	1	\$ 32.00	
42	BONNET ENGINE SOUND ABSORBER	1	\$ 223.00	
43	BONNET STRIKER - RH	1	\$ 130.00	
44	BONNET LOCK - RH	1	\$ 241.00	
45	BONNET RELEASE ELEMENT	1	\$ 69.00	
46	BONNET RELEASE LEVER	1	\$ 16.00	
47	BONNET BOWDEN CABLE - CENTER	1	\$ 66.00	
48	BONNET RELEASE CABLE COVER	1	\$ 12.00	
49	FRONT PLENUM CHAMBER COVER	1	\$ 187.00	
50	HEADLIGHT - RH	1	\$ 4,323.00	\$ 3,458.40
51	HEADLIGHT HOSE - RH	1	\$ 29.00	
52	LIFT CYLINDER - RH	1	\$ 223.00	
53	LIFT CYLINDER HOSE	1	\$ 112.00	
54	LOCK CARRIER	1	\$ 1,030.00	
55	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 22.00	
56	READY-MIX COOLANT	6	\$ 326.00	
57	RADIATOR AIR GUIDE - RH	1	\$ 45.00	
58	RADIATOR AIR GUIDE SEAL - RH	1	\$ 15.00	
59	RADIATOR AIR GUIDE - LOWER CENTRE	1	\$ 61.00	
60	REAR BUMPER	1	\$ 2,026.00	
SUB TOTAL SPARE PARTS		:	\$ 9,188.00	\$ 7,253.60

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 1979 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		C/F		\$	7,253.60
61	REAR BUMPER FIXING PARTS	1	\$ 348.00		
62	REAR BUMPER LOCKING MECHANISM - RH	1	\$ 17.00		
63	REAR BUMPER GUIDE SECTION - RH	1	\$ 66.00		
64	REAR PARKING AID SENSOR - RH	1	\$ 286.00		
65	REAR PARKING AID SEAL RING	1	\$ 14.00		
66	REAR WHEEL HOUSING LINER - RH	1	\$ 281.00		
67	FRONT AND REAR ALUMINIUM RIM - RH	2	\$ 3,038.00	\$	1,215.20
68	FRONT ASSEMBLY CARRIER	1	\$ 834.00	\$	667.20
69	BONDED RUBBER BUSHES	1	\$ 181.00	\$	144.80
70	FRONT LOWER CONTROL ARM - RH	1	\$ 396.00	\$	316.40
71	FRONT STABILIZER	1	\$ 470.00		
72	FRONT WHEEL BEARING HOUSING - RH	1	\$ 642.00	\$	513.20
73	FRONT WHEELHUB WITH BEARING	1	\$ 554.00	\$	443.20
74	FRONT GUIDE JOINT - RH	1	\$ 138.00	\$	110.00
75	FRONT COUPLING ROD	1	\$ 106.00	\$	84.40
76	FRONT JOINTED SHAFT - RH	1	\$ 1,548.00	\$	1,238.40
77	FRONT GAS SHOCK ABSORBER	1	\$ 469.00	\$	374.80
78	FRONT STEERING GEAR WITH TRACK RODS	1	\$ 5,916.00		
79	FRONT TRACK ROD	1	\$ 107.00	\$	85.60
80	FRONT TIE ROD END - RH	1	\$ 132.00	\$	105.20
SUB TOTAL SPARE PARTS		:	\$ 15,543.00	\$	12,552.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 1979 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		C/F		\$ 12,552.00
81	FRONT NOISE INSULATION	1	\$ 408.00	
82	REAR WINDOW SLOT SEAL TRIM STRIP - RH OUTER	1	\$ 274.00	
83	REAR WINDOW GUIDE TRIM STRIP - RH	1	\$ 314.00	
84	FRONT NUMBER PLATE	S/N	\$ 60.00	
85	RHS FRONT TYRE	S/N	TBC	\$ 300.00
86	SUNDRIES		\$ 1,000.00	\$ 235.12
TOTAL SPARE PARTS			\$ 39,814.00	\$ 13,087.12
TOTAL LABOUR CHARGES			\$ 20,734.00	\$ 10,334.00
GRAND TOTAL			\$ 60,548.00	\$ 23,421.12

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-10/04/23



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0236/2023/EQ 15-Mar-23 CHANG 1 of 1 SMA 1979 K AUDI A3 SPORTBACK 1.5 TFSI	
Quantity	Description		Unit Price	Amount
<u>Parts</u>				
1	AERIAL FOR ACCESS	1	\$ 100.00	<i>sundry</i>
	GRAND TOTAL		\$ 100.00	

For Premium Automobiles Pte Ltd

Authorised Signature



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT