



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD		Ref:	CS3/SMR22010711/Dwy3e2-1
60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Date:	08/03/2023
		Code:	SMR
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 89P	Veh. Inspected	FBS 7584L
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/10/22/2069	Excess (\$)	0.00
Assign From	ANA MAGNAYE	Assign Date	21/02/2023
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA T155	c.c	155
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	RLCUG1610MY001195	Colour	BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	80/90-17	PIRELLI	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90-17	PIRELLI	5 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/10/2022	Inspection Date	28/10/2022
Survey held at	TUNE IN MOTOR BLK 1016 YISHUN PARK A #01-214 SINGAPORE 768758		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	