



INVOICE

TO : IRWAN BIN HUSSIN
C/O: TUNE IN MOTOR COMPANY
BLK 1016 YISHUN
INDUSTRIAL PARK A #01-214
SINGAPORE 768758

Invoice No.: 1022/TI303
Date: 25-Nov-2022

PARTICULARS

Vehicle Registration No.: FBS 7584 L
Date of Loss: 22-Oct-2022
Date of Assessment: 27-Oct-2022

SERVICES

FEES

1. Assessment with report Photographs -
Including films, developing, storage and Transport. \$400.00

TOTAL \$400.00

SINGAPORE DOLLARS FOUR HUNDRED ONLY

We would appreciate your cheque crossed and made payable to:
"AEON AUTO CONSULTANTS LLP" with our invoice no. written on the back of the cheque.

AEON AUTO CONSULTANTS LLP



AEON AUTO CONSULTANTS LLP

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874
Tel: +65 97687958 Fax +65 68264112 Email amas@aeonac.com.sg/amasopm@gmail.com
Reg. No. T07LL1273E (registered with limited liability)

AUTOMOBILE ASSESSMENT REPORT

TO: IRWAN BIN HUSSIN
C/O: TUNE IN MOTOR COMPANY
BLK 1016 YISHUN
INDUSTRIAL PARK A #01-214
SINGAPORE 768758

Our Reference: 1022/TI303
Date: 25-Nov-2022

ASSESSMENT OF VEHICLE NO. FBS 7584 L
DATE OF LOSS: 22-Oct-2022

We have carried out a physical assessment at **TUNE IN MOTOR COMPANY**,
Blk 1016 Yishun Industrial Park A #01-214, Singapore 768758, according to your instruction
of **27-Oct-2022** and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.: FBS 7584 L
Make & Model: YAMAHA T155
Year of Registration: 2021
Engine Capacity: 155
Chassis No.: RLCUG1610MY001195
Engine No.: G3R9E001192
Colour: BLUE

2. VEHICLE CONDITION

Body Paint: GOOD
Steering: SERVICEABLE
Foot Brake: SERVICEABLE
Parking Brake: SERVICEABLE
Modification: NIL

3. TYRE PARTICULARS & CONDITION

Front
Make/Size/Thread: PIRELLI 80/90 R17 – 75%

Rear
Make/Size/Thread: PIRELLI 80/90 R17 – 75%

4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the L/R portion.

5. REMARKS

Market Value: Na
Salvage Value: Na
Repair Limit: Na

Estimated Amount: \$6,289.50
Adjusted Amount: \$4,201.15
Final Adjusted Sum: \$3,500.00
Estimated Repair Days: 8 days
Date of Completion : 11-Nov-2022



Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a "Without Prejudice" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

ASSESSMENT REPORT FOR VEHICLE NO. FBS 7584 L

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	SIDE MIRROR L/R - SET	Cracked	128.00	100✓128.00
1	HEADLAMP ASSY	Repair	352.00	- X nn
1	HANDLE BAR	Bent	128.00	85✓128.00
1	HANDLE GRIP L/R - SET	Cracked	78.00	35✓78.00
1	HANDLE BAR BALANCER L/R - SET	Cracked	68.00	30✓68.00
1	HANDLE LEVER RH	Bent	78.00	30✓78.00
1	HANDLE LEVER LH	Repair	78.00	- X nn
1	FRONT FORK ASSY	Repair	622.00	- X nn
1	FRONT WHEEL SHAFT	Bent	58.00	58.00 X nn
1	FRONT WHEEL BEARING	Jammed	88.00	88.00 X nn
1	FRONT WHEEL	Repair	285.00	- X nn
1	BODY COVERSET - SET	Cracked	885.00	450✓885.00
2	FRONT SIGN LAMP L/R	Cut	148.00	130✓148.00
1	FRONT FOOTREST L/R - SET	Cracked	98.00	98.00✓
1	FRONT FOOTREST BRACKET	Bent	168.00	80✓168.00
1	FRONT LH GEAR SHIFT LEVER	Bent	98.00	98.00 X nn
1	SIDE STAND	Bent	128.00	70✓128.00
1	REAR LH FOOTREST	Cut	68.00	68.00 X nn
1	REAR LH FOOTREST BRACKET	Repair	128.00	- X nn
1	EXHUAUST PROTECTOR COVER - SET	Cracked	198.00	80✓198.00
1	EXHAUST PIPE	Repair	428.00	- X nn

1188
-10%
1069.20

Less 5% discount
Parts Total:

4,310.00	2,417.00
215.50	120.85
4,094.50	2,296.15

ASSESSMENT REPORT FOR VEHICLE NO. FBS 7584 L

SPECIAL NETT ITEMS

1	REAR TOP BOX	Cut	185.00	185.00	✓
1	REAR TOP BOX BRACKET/RAIL SET	Bent	80.00	80.00	✗ nn
185					
Special Nett Total :			265.00	265.00	

LABOUR

	Description		Workshop's Estimate	Our Assessment	
1	Check wiring system and light.		80.00	60.00	30
2	Wheel alignment.		100.00	80.00	50
3	To check, align and balance body main frame.		250.00	200.00	150
4	Spray painting.		600.00	500.00	200
5	Labour for repair and replace parts.	680	900.00	800.00	250
Labour Total :			1,930.00	1,640.00	
TOTAL (PARTS & LABOUR) \$			6,289.50	4,201.15	

The workshop has agreed to undertake the repair cost of the final adjusted Sum contract amount is

\$3,500.00 (SINGAPORE DOLLARS THREE THOUSAND FIVE HUNDRED ONLY)

1934.20

**L/S - 1547.36
= 1550**

3 days



Amas Ong
Automobile Assessor