LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01 Singapore 068897

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Sharon Lim 13 Mar 2023 Attn: Date:

Preliminary Advice

Vehicle No : SKE9939B Accident Date : 03/03/2023 Make : NISSAN QASHQAI Policy No. : SP2003092123 Assignment Date : 06/03/2023 **Excess** : S\$600.00

Date of Inspection : 10/3/2023 Est. Duration of Repair : 6

Inspection At : KAN FOOK SING MOTOR WORKSHOP

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 10,313.00 |
|-----------------------------|------|-----------|
| Revised Amount | :S\$ | 4,290.50 |
| Check Items (Estimated) | :S\$ | 5,229.50 |
| Total | :S\$ | 9,520.00 |

Lump Sum Repair :S\$

Total Loss Consideration

0111/1

| New for Old Value | :5\$ | |
|--------------------|------|-----------|
| Pre-Accident Value | :S\$ | 60,000.00 |
| COE / PARF Rebate | :S\$ | 31,826.00 |

Salvage Value :S\$

Margin for Repair :S\$ 28,174.00

Remarks

| (X) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let |
|-------|-----------------------------------------------------------------------------------------------------------------|
| | us have your authorisation. |

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Part by part repair as there is no 2nd hand parts available

> Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.