

ASS. REP. U.D. Taufan

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp. ed Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: \$600

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$60K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: SUE9939B

Yr Regn: 2016, Oct

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Nissan Qashqai

C.C. 1997

Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 117680

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SJNF15A31141702577

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N/S / Rim / STD A/Rim or

Tyre Size: F: 225/45R19

R: N/A

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIRI / SUMI /

TOYO / YOKO or Guerlander

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

D.O.I. 10/3/23

Survey held at KFS

Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1) Date/Time, File Return to?

☐ : Final Report

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

Report Format: _____

Lump Sum / L.B.R. / _____



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, Singapore 533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2003092123	Date of Loss:	03/03/2023
Vehicle Reg. No.:	SKE9939B	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SEAH SWEE HENG(XIE RUIXNG)		
Make/Model:	NISSAN QASHQAI, 2.0 CVT (A)	Vehicle Reg. Date:	17/10/2016
Vehicle Colour:	METALLIC GREY	Chassis No:	SJNFBAJ11U1752577
Engine No:	MR20425732W		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS	Amount
Parts	8,503.00
Miscellaneous Items	40.00
Labour	950.00
Paintwork Labour	820.00
Towing	0.00
Calculated Gross Total (S\$)	10,313.00
- Excess (S\$)	600.00
(S\$)	9,713.00
+ GST 8.00% (S\$)	777.04
Nett Amount (S\$)	10,490.04

This claim is handled by: MT TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Mar 2023)

Parts: M1-SUV NISSAN QASHQAI 2.0 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/SKE9939B/06/03/2023 10:26

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET	0.00	0.00	bt *600.00 F
2	1		*FRONT BONNET LOCK	0.00	0.00	? *70.00 F
3	1		*FRONT BONNET SEAL	0.00	0.00	? *140.00 F
4	1		*FRONT TOP PANEL	0.00	0.00	? *450.00 F
5	1		*FRONT TOP PANEL GARNISH	0.00	0.00	? *75.00 F
6	8		*FRONT TOP PANEL GARNISH CLIP	0.00	0.00	? *20.00 F
7	1		*FRONT HEADLAMP PANEL RH	0.00	0.00	? *75.00 F
8	1		*FRONT HEADLAMP PANEL LH	0.00	0.00	? *75.00 F
9	1		*FRONT HEADLAMP RH	0.00	0.00	? *1,200.00 F
10	1		*FRONT HEADLAMP LH	0.00	0.00	am *1,200.00 F
11	1		*FRONT HEADLAMP LOWER BRACKET RH	0.00	0.00	? *75.00 F
12	1		*FRONT HEADLAMP LOWER BRACKET LH	0.00	0.00	? *75.00 F
13	1		*FRONT GRILLE	0.00	0.00	? *350.00 F
14	1		*FRONT GRILLE EMBLEM	0.00	0.00	? *60.00 F
15	1		*FRONT FENDER RH	0.00	0.00	Ry *380.00 F
16	1		*FRONT FENDER LH	0.00	0.00	bt *380.00 F
17	1		*FRONT FENDER WHEEL ARCH GARNISH RH	0.00	0.00	? *250.00 F
18	1		*FRONT FENDER WHEEL ARCH GARNISH LH	0.00	0.00	? *250.00 F
19	20		*FRONT FENDER SHIELD CLIP	0.00	0.00	x *50.00 F
20	1		*FRONT BUMPER	0.00	0.00	de *400.00 F
21	1		*FRONT BUMPER SIDE RETAINER RH	0.00	0.00	de *25.00 F
22	1		*FRONT BUMPER SIDE RETAINER LH	0.00	0.00	de *25.00 F
23	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	? *380.00 F
24	10		*FRONT BUMPER CLIP	0.00	0.00	de *25.00 F
25	1		*AIR CON CONDENSER	0.00	0.00	? *550.00 F
26	1		*RADIATOR	0.00	0.00	? *550.00 F

F=Franchise part.

Sub Total (S\$)	7,730.00
+ Margin on L,N Items 10.00% (S\$)	773.00
Total Parts (S\$)	8,503.00

Kan Fook Sing Motor Workshop/SKE9939B/06/03/2023 10:26. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 FRONT NUMBER PLATE

40.00

Sub Total (S\$)

40.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1 SPRAYPAINTING CHARGES

New

700

820.00

Labour Items

2 TO CHECK WIRING SYSTEM

New

30

50.00

3 TO REMOVE/REFIT/REFILL AIR CON GAS

New

600

120.00

4 TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS

New

600

780.00

Gross Labour Cost (S\$)

1,770.00

Kan Fook Sing Motor Workshop/SKE9939B/06/03/2023 10:26. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanfah 97495719/62563561
Not Advise 6/3/23 10/10am
Ex 600

tanfah@khauto.com

p/p Resurvey before paint
6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: