

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002365/SVP3Q2**Date:** 09/06/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00194582200

Claimant Vehicle No : FBM559M **Insured Vehicle No :** SFL9659G

Date of Loss: 10/02/2023 Nature of Claim: TP Claim No: SNM23D201091/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBM559M**

Make & Model: HONDA FS150F, 149cc Engine No: KC27E2018785

Reg. Date: 22/06/2017 (Man. Year: 2017) Chassis No: PMKKC27C0HB010025

Colour: Orange Odometer: 0 km

Engine Capacity: 149 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 80/90-17 Rear Tyre Size: 120/70-17

Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,097.00	791.10	305.90	27.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	660.00	310.00	350.00	53.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,757.00	1,101.10	655.90	37.33
Approved Total (Overridden) (S\$)		900.00		
(S\$)	1,757.00	900.00	857.00	48.78
+ GST 8.00/8.00% (S\$)	140.56	72.00	68.56	48.78
Nett Amount (S\$)	1,897.56	972.00	925.56	48.78

INSPECTION

Date of Assignment: 13/04/2023

Date Inspected: 06/03/2023 Inspected At: Global Motor Pte Ltd (HQ)
BLK 53 UBI AVENUE 1 #01-12
Singapore 408934

Estimated Period of Repair: 3.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 08 Jun 2023)	
Parts:	N/A	HONDA FS150F 149cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBM559M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRAKE LEVER	Broken	38.00 F	*38.00 FL
2	1		*RIGHT SIGNAL LIGHT	Broken	65.00 F	*55.00 FL
3	1		*HANDLE BAR BALANCER	Scratched	28.00 F	*28.00 FL
4	1		*RIGHT INNER COVER	Scratched / Cut	98.00 F	*98.00 FL
5	1		*RIGHT OUTER COVER	Scratched / Cut	220.00 F	*110.00 FL
6	1		*CENTRE COVER	Scratched / Cut	110.00 F	*110.00 FL
7	1		*FRONT MUDGUARD	Scratched / Cut	130.00 F	*130.00 FL
8	1		*EXHAUST PIPE COVER	Broken	85.00 F	*65.00 FL
9	1		*EXHAUST COVER BACK	Scratched / Cut	55.00 F	*55.00 FL
10	1		*RIGHT MIRROR	Scratched / Cut	48.00 F	*40.00 FL
11	1		*BOX	Scratched / Cut	220.00 F	*150.00 FL
					F=Franchise part. L=ListItemDisc.	
					Sub Total (\$\$)	1,097.00 879.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 87.90
					Total Parts (\$\$)	1,097.00 791.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE	New	300.00	200.00
2	REPAIR FOLK	New	280.00	80.00
3	TRANSPORT FEE	New	80.00	30.00
Gross Labour Cost (S\$)			660.00	310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >