

ASS. REC. BY:

REF:

MSG/ 230023701K

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

21

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SKZ 44980

Yr Regn:

01, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota AIAJ

c.c

1598

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

289268

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053REH104543761

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

3/3/23

D.O.I.

9/3/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

F. m

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SKZ4498D

TP/mslg

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

Not Authorised

WS Ref: TP MSIG

Claim Type: Third Party

Accident Date: 03/03/2023

TP Veh Reg No: GBF9850Z

*11 Day @
Recovery After Repair
21 day*

Estimate No: ES2300236/WL

Date: 07 Mar 2023

Policy No:

Veh Reg No: SKZ4498D

Make/Model: TOYOTA TOYOTA
COROLLA ALTIS

Chassis No: MR053REH104543761

Engine No:

Reg. Date: 25/01/2016

Estimate Repair Cost to Vehicle No :SKZ4498D

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER	704.30	1 PC	<i>Bu</i> 704.30 ✓	
2 FRONT BUMPER REINFORCEMENT	480.20	1 PC		✓
3 FRONT BUMPER SPONGE	107.60	1 PC	<i>CM</i> 107.60	✓
4 FRONT BUMPER RH SIDE RETAINER	102.60	1 PC	<i>DIT</i> 102.60	✓
5 FRONT BUMPER CLIPS	3.50	6 PCS	<i>me</i> 21.00	✓
6 FRONT GRILLE	770.80	1 PC	<i>my</i> 770.80	✓
7 FRONT GRILLE LOGO	72.20	1 PC	<i>my</i> 72.20	✓
8 FRONT GRILLE CLIPS	3.50	4 PCS	<i>me</i> 14.00	✓
9 BONNET	1,418.40	1 PC	<i>Bu</i> 1,418.40	✓
10 BONNET INNER LOCK	162.20	1 PC	<i>DIT</i> 162.20	✓
11 BONNET INNER RUBBER	60.80	1 PC	<i>my</i> 60.80	✓
12 FRT SUPPORT PANEL	1,364.40	1 PC	<i>Bu</i> 1,364.40	✓
13 FRT BRACE PANEL	149.50	1 PC	<i>DIT</i> 149.50	✓
14 RH HEADLAMP	3,604.30	1 PC	<i>my</i> 3,604.30	✓
15 AIR-CON CONDENSER	2,162.20	1 PC		✓
16 RADIATOR	2,581.80	1 PC		✓
17 FRONT RH FENDER	1,091.50	1 PC	<i>Bu</i> 1,091.50	✓
18 FRONT RH FENDER EMBLEM (VVTI)	70.80	1 PC	<i>me</i> 70.80	✓
19 REAR BUMPER	669.10	1 PC	<i>Bu</i> 669.10	✓
20 REAR BUMPER RH SIDE RETAINER LONG	131.80	1 PC	<i>CM</i> 131.80	✓
21 REAR BUMPER RH SIDE RETAINER SHORT	102.10	1 PC	<i>CM</i> 102.10	✓
22 REAR BUMPER RH REFLECTOR	72.20	1 PC		✓
23 REAR BUMPER CLIPS	3.50	6 PCS	<i>me</i> 21.00	✓
24 REAR BOOT	947.10	1 PC	<i>Bu</i> 947.10	✓
25 REAR BOOT LOGO	70.80	1 PC	<i>me</i> 70.80	✓
26 REAR BOOT OUTER MOULDING	292.50	1 PC	<i>CM</i> 292.50	✓
27 REAR BOOT EMBLEM (COROLLA)	70.80	1 PC	<i>me</i> 70.80	✓
28 REAR BOOT EMBLEM (ALTIS)	70.80	1 PC	<i>me</i> 70.80	✓
29 REAR BOOT INNER LOCK	480.20	1 PC	<i>DIT</i> 480.20	✓
30 REAR BOOT INNER RUBBER	211.10	1 PC		50% ✓
31 REAR BOOT HINGES	83.00	2 PCS	<i>me</i> 166.00 ✓	

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
 16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581
 TEL: 68277660 FAX: 62257402
 ATTN: Motor Claim Department

WS Ref: TP MSIG
 Claim Type: Third Party
 Accident Date: 03/03/2023
 TP Veh Reg No: GBF9850Z

Estimate No: ES2300236/WL
 Date: 07 Mar 2023
 Policy No:
 Veh Reg No: SKZ4498D
 Make/Model: TOYOTA TOYOTA
 COROLLA ALTIS
 Chassis No: MR053REH104543761
 Engine No:
 Reg. Date: 25/01/2016

Estimate Repair Cost to Vehicle No :SKZ4498D

Description	U/Price	Quantity	List Price	Amount
			SS	SS
32 REAR BOOT INNER SPONGE	437.20	1 PC	Return 437.20	✓
33 REAR BOOT INNER SPONGE CLIPS	3.50	6 PCS	Mc 21.00	✓
34 REAR END PANEL	808.00	1 PC	R 808.00	✓
35 REAR END PANEL INNER TOP GARNISH	290.40	1 PC	D11 290.40	✓
36 REAR END PANEL INNER TOP GARNISH LOCK COVER	49.10	1 PC	M11 49.10	✓
37 REAR TYRE COMPARTMENT	877.00	1 PC	R1 877.00	✓
38 REAR TYRE COMPARTMENT TOP BOARD	320.30	1 PC	CR1 320.30	✓
39 REAR TYRE COMPARTMENT RH EXTENSION	86.40	1 PC	R1 86.40	✓
40 REAR RH FENDER	1,382.30	1 PC	Return 1,382.30	✓
41 REAR RH FENDER INNER GARNISH	445.30	1 PC	445.30	✓
42 REAR RH FENDER INNER SHIELD	70.80	1 PC	70.80	✓
43 RH TAILLAMP	456.10	1 PC	CM 456.10	✓
44 RH TAILLAMP PANEL	133.80	1 PC	R1 133.80	✓
45 REAR RH FENDER AIR DUCT	164.30	1 PC	164.30	✓
46 REAR EXHAUST PIPE	1,249.90	1 PC	1,249.90	✓
47 CENTRE EXHAUST PIPE	4,079.00	1 PC	4,079.00	✓
48 FRONT LH DOOR OUTER HANDLE	96.80	1 PC	(Gr) 96.80	X
			29,211.80	
		Less 25%	7,302.95	21,908.85
Special Net				
49 REAR WINDSCREEN GLASS GUM	40.00	1 PC	Mc 40.00	✓
			40.00	40.00
Labour				
50 TOWING (BY OWNER)	130.00	1 LA	(Bill) 130.00	✓
51 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
52 REMOVE & REFIX FRT BUMPER ASSY,HEADLAMPS,GRILLE,FRT FENDERS,BONNET & ATTACHMENT,RADIATOR & MOTOR,TO CUT,WELD & RENEW FRT SUPPORT PANEL,KNOCK & REPAIR FRT LH FENDER AND REALIGN THE SAME	900.00	1 LA	900.00	600.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660 FAX: 62257402
ATTN: Motor Claim Department

WS Ref: TP MSIG
Claim Type: Third Party
Accident Date: 03/03/2023
TP Veh Reg No: GBF9850Z

Estimate No: ES2300236/WL
Date: 07 Mar 2023
Policy No:
Veh Reg No: SKZ4498D
Make/Model: TOYOTA TOYOTA
COROLLA ALTIS
Chassis No: MR053REH104543761
Engine No:
Reg. Date: 25/01/2016

Estimate Repair Cost to Vehicle No :SKZ4498D

Description	U/Price	Quantity	List Price	Amount
53 PUTTY & RESPRAY ON FRT SUPPORT PANEL,FRT BUMPER,REINFORCEMENT,FRT FENDERS,BONNET,HINGES	900.00	1 LA	900.00	800
54 REMOVE & REFIX REAR BUMPER ASSY,TAILLAMPS,REAR BUMPER,REAR BOOT & ATTACHMENT,TO CUT,WELD & RENEW REAR RH FENDER,REAR SPARE TYRE COMPARTMENT,KNOCK & REPAIR REAR RH DOOR,REAR RH CHASSIS,REAR LH FENDER & REALIGN THE SAME	2,200.00	1 LA	2,200.00	2000
55 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
56 PUTTY & RESPRAY ON REAR BUMPER,REINFORCEMENT,REAR PANEL,REAR BOTH FENDERS,REAR COMPARTMENT,REAR BOTH CHASSIS,BOOT,HINGES,REAR RH DOOR	1,800.00	1 LA	1,800.00	1400
57 TO REMOVE & REFIX EXHAUST AND CHECK SYSTEM	100.00	1 LA	100.00	80
58 RUSTPROOFING	100.00	1 LA	100.00	✓
			6,330.00	6,330.00
			Total	S\$ 28,278.85
			Add GST @ 8%	2,262.31
			Total Amount Payable	S\$ 30,541.16

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

224D

Vehicle Details

Vehicle No.:

SKZ4498D

Vehicle to be Exported:

No

Intended Deregistration Date:

03 Mar 2023

Vehicle Make:

TOYOTA

Vehicle Model:

TOYOTA COROLLA ALTIS 1.6L CVT

Primary Colour:

Silver

Manufacturing Year:

2015

Engine No.:

1ZRX546097

Chassis No.:

MR053REH104543761

Maximum Power Output:

90.0 kW (120 bhp)

Open Market Value:

\$19,589.00

Original Registration Date:

25 Jan 2016

First Registration Date:

25 Jan 2016

Transfer Count:

1

Actual ARF Paid:

\$19,589.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

24 Jan 2026

PARF Rebate Amount:

\$11,753.00

Intended COE Rebate Details

COE Expiry Date:

24 Jan 2026

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$45,002.00

COE Rebate Amount:

\$13,004.00

Total Rebate Amount:

\$24,757.00

SKZ 4498D
7P/M416

The information contained herein is correct as at 03 Mar 2023

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 06/03/2023 11:43 (SGT)
Reported by Both Policyholder and Actual Driver
Date of Accident 03/03/2023 13:45 (SGT)
Exact Location of Accident Singapore
Additional Location Information ECP TOWARDS CHANGI AFTER BAYSHORE ROAD
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKZ4498D
INSURED/POLICYHOLDER
Is company? No
Name Of Registered Owner CHOONG LAI WAN
NRIC No SXXXX224D
Email Address choonlaiwan68@gmail.com
Mobile Phone No (Phone) +65-91128366
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Toyota
Model TOYOTA COROLLA ALTIS 1.6L CVT
Variant -
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private hire
Transmission Auto
CC 1598

INSURANCE COMPANY

Name of Insurance Company Income Insurance Limited
Policy Number / Cover Note Number 5121492407-02

DRIVER


Name of Driver CHOONG LAI WAN
NRIC No SXXXX224D
Date Of Birth 13/09/1968
Occupation Outdoor

Describe Circumstance of the Accident

NOTE PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14 DAYS TIME FRAME for you to submit OWN DAMAGE Claim under your Own Comprehensive policy. Pls check your policy for more information.

() Claim Own Policy (☒) Claim Third party () Reporting Only
() Claim OD/ TP at other workshop ()

Sketch Plan



Refer Police Report at
T/20230303/7089

Declaration

I/We declare the foregoing particulars are true in every respect.

Zmwa

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Wale 3/3/23

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

W