

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBC8011B

Model : SYM GTS200

S/N	Parts Description	QTY	List Price	Nett Price	Remark
1	Mirror (L) <i>SCA /</i>		\$ 145.00		
2	Front cover <i>cm /</i>		\$ 385.00		
3	Front signal lamp <i>SCA /</i>		\$ 88.00		
4	Lower cover <i>cm /</i>		\$ 280.00		
5	Inner compartment <i>cm /</i>		\$ 320.00		
6	Coolant maintance cover <i>cm MI, /</i>		\$ 220.00		
7	Foot board <i>cm /</i>		\$ 190.00		
8	Rear foot rest <i>SCA /</i>		\$ 75.00		
9	Tail cover <i>SCA /</i>		\$ 275.00		
10	Kick starter lever ? <i>bt /</i>		\$ 80.00		
11	Air filter box <i>SCA /</i>		\$ 160.00		
12	Rear fender <i>SCA /</i>		\$ 150.00		
13	Handle bar ? <i>bt /</i>		\$ 220.00		
14	Handle balancer <i>SCA /</i>		\$ 50.00		
15	Brake lever <i>SCA /</i>		\$ 45.00		
16	Handle cover ? <i>X an</i>		\$ 150.00	X	
17	Front fender <i>SCA /</i>		\$ 180.00		
18	Fork assy <i>SCA /</i>		\$ 850.00		
19	Fork under bracket ? <i>bt /</i>		\$ 320.00		
20	Steering cone & bearing ? <i>an</i>		\$ 150.00		
21	Front wheel rim <i>repair</i>		\$ 350.00	X	
22	Front wheel bearing ? <i>X an</i>	2	\$ 50.00	X	
23	Front brake disc plate <i>SCA /</i>		\$ 195.00		
24	Rear box <i>SCA /</i>			\$ 200.00	150
25	Rear box base <i>cm /</i>			\$ 80.00	50
26	Rear no plate <i>bt /</i>			\$ 20.00	15
27	Repair alignment			\$ 350.00	250
28	Towing 2 way 1 receipt (1 way)			\$ 100.00	5
29	Labour			\$ 450.00	300
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Less 10%

\$ 4,928.00 \$ 1,200.00

\$ 492.80

\$ 4,435.20

45-\$3850 / 5 days

Hp 90010068

90010068

5 days

L/S

06/03/23 @ 1210

Rong after repair