

# JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778  
E-mail:jlperfectautowork@gmail.com



DATE : 20.02.2023

TO : **AIG** MOTOR CLAIMS DEPTS  
VEHICLE NO : **SKZ848D**  
MODEL : **TOYOTA COROLLA ALTIS**  
DATE OF ACCIDENT : 24.01.2023  
TIME OF ACCIDENT : 17:54 HOURS

MR053REH104543641

Erlyan

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

### CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	REAR BUMPER <i>Rehd</i>	1	\$ 515.10	\$ 515.10	-
2	REAR BUMPER REFLECTOR <i>Not new</i>	2	\$ 75.10	\$ 150.20	+ 56
3	REAR BUMPER SIDE RETAINER <i>RH Rhd</i>	2	\$ 105.10	\$ 210.20	<del>103.40</del>
4	REAR BUMPER REINFORCEMENT <i>Rehd</i>	1	\$ 395.10	\$ 395.10	-
5	REVERSE SENSOR <i>1 piece damaged</i>	2	\$ 311.10	\$ 622.20	+ 265
6	REVERSE SENSOR HOLDER <i>New</i>	2	\$ 69.30	\$ 138.60	+ 50
7	REVERSE SENSOR WIREHARNES <i>New</i>	1	\$ 437.50	\$ 437.50	+ 4
8	BOOTLID <i>Repair</i>	1	\$ 756.10	\$ 756.10	+ 4
8	BOOTLID LAMP <i>3 MP</i>	1	\$ 342.00	\$ 342.00	+ 4
9	BOOTLID DETECTOR <i>3 MP</i>	1	\$ 385.00	\$ 385.00	+ 4
10	BOOTLID LOGO <i>3 MP</i>	1	\$ 85.00	\$ 85.00	-
11	BOOTLID EMBLEM 'COROLLA' <i>3 MP</i>	1	\$ 70.00	\$ 70.00	-
12	BOOTLID EMBLEM 'ALTIS'	1	\$ 70.00	\$ 70.00	-
13	BOOT LID HINGE <i>2 MP</i>	2	\$ 70.00	\$ 140.00	+ 4
14	BOOTLID TOP LOCK <i>3 MP</i>	1	\$ 318.10	\$ 318.10	+ 4
15	BOOTLID LOWER LOCK <i>3 MP</i>	1	\$ 20.00	\$ 20.00	+ 4
16	BOOTLID WEATHERSTRIP	1	\$ 195.00	\$ 195.00	+ 4
17	TAILLAMP RH <i>Rehd</i>	1	\$ 465.00	\$ 465.00	-
18	TAILLAMP LOWER BARCKET RH <i>Not new</i>	1	\$ 115.10	\$ 115.10	+ 4
19	REAR FENDER INNER COWLING RH <i>New</i>	1	\$ 350.20	\$ 350.20	+ 4
20	REAR FENDER INNER TRIM RH <i>Not new</i>	1	\$ 770.10	\$ 770.10	+ 4

TO : **AIG** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SKZ848D**  
 MODEL : **TOYOTA COROLLA ALTIS**  
 DATE OF ACCIDENT : 24.01.2023  
 TIME OF ACCIDENT : 17:54 HOURS

21	REAR END PANEL <i>Dented</i>	1	\$ 695.30	\$ 695.30	<i>+</i>
22	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 250.10	\$ 250.10	<i>+</i>
23	REAR FLOOR PANEL TOP BOARD <i>New</i>	1	\$ 271.10	\$ 271.10	<i>+</i>

*2916.60*  
*2187.45*

TOTAL PRICE \$ 7,767.00  
 LESS 25% \$ 1,941.75  
**SUB TOTAL PRICE \$ 5,825.25**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>New</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
2	REAR BUMPER CLIPS (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
3	BOOT LID INSULATOR CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
4	TAILLAMP CLIPS (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	<i>20</i>
5	REAR FENDER COWLING CLIPS (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
6	REAR FENDER INNER TRIM CLIPS (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
7	REAR END PANEL TOP GARNISH CLIPS (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	<i>20</i>
8	REAR END PANEL INSULATION SEAL <i>New</i>	1	\$ 150.00	\$ 150.00	<i>60</i>

*130*

**TOTAL \$ 660.00**

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	<i>600</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	<i>600</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING CHECK	\$ 200.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 200.00	<i>60</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 100.00	<i>50</i>
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 100.00	<i>X</i>

TO : **AIG** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SKZ848D**  
 MODEL : **TOYOTA COROLLA ALTIS**  
 DATE OF ACCIDENT : 24.01.2023  
 TIME OF ACCIDENT : 17:54 HOURS

8	TRANSFER BOOTLID MECHANISM	\$ 100.00	X
9	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	X

1400

**TOTAL \$ 3,900.00**

TOTAL PARTS COST : \$ 6,485.25  
 TOTAL LABOUR COST : \$ 3,900.00  
 TOTAL REPAIR COST : \$ 10,385.25

*Adrian King*  
*2/5 20/02/23*  
*05 Days*

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

**PARTS PRICES ARE SUBJECT TO CHANGES.**

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
 IRENE  
 HP:8297 9787

*total: 3717.45*  
*4/5: 2950 ✓*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: