

2000 H5.40 Tony

Not Full
7/3/23
1/5 \$ 3200
4 days.

SPEEDWERKZ PRIVATE LIMITED

1 Kaki Bukit Avenue 6 #01-73 Singapore 417883

Tel: 96195936 / info@speedwerkz.biz

VEHICLE NUMBER: SMF3171J
MAKE & MODEL: HONDA FIT HYBRID
DOA: 6/3/2023
CLAIM TYPE: TP CLAIM

PARTS	QTY	PRICE (\$)	REMARKS
Rear boot cover 862.50	1	\$ 1,038.20	DD/SH ✓
Rear boot lock 168.20	1	\$ 456.90	DD ✓
Rear boot lock catch	1	\$ 78.50	11 X
Rear boot centre garnish	1	\$ 259.20	11 X
Rear boot centre logo	1	\$ 65.00	11 X
Rear boot absorber @ 156.70	2	\$ 313.40	11 X
Rear boot inner cover board	1	\$ 225.00	11 X
Rear boot side trim @165.20	2	\$ 330.40	11 X
Rear boot centre trim	1	\$ 215.20	11 X
Rear boot hinge @ 95.20	2	\$ 190.40	11 X
Rear boot rubber 145.80	1	\$ 306.40	7m ✓
Rear boot emblem (FIT)	1	\$ 49.20	11 ✓
Rear tail lamp @ 625.60	2	\$ 1,251.20	11 X
Rear tail lamp panel @185.60	1	\$ 371.20	R X
Rear end penal 349.20	1	\$ 558.00	DD/SH ✓
Rear end penal top garnish 166.80	1	\$ 199.00	11 ✓
Rear spare tyre panel	1	\$ 947.60	R X
Rear spare tyre panel tool tray sponge	1	\$ 285.20	11 X
Rear spare tyre panel top cover board	1	\$ 229.30	7m ✓
Rear fender @ 985.20	2	\$ 1,970.40	11 X
Rear fender inner garnish @334.90	2	\$ 669.80	11 X
Rear fender under shield @84.90	2	\$ 169.80	11 X
Rear fender air duct @38.80	2	\$ 77.60	11 X
Rear bumper 585.20	1	\$ 996.30	DD/SH ✓
Rear bumper side retainer @ 37	2	\$ 74.00	11 ✓
Rear bumper tow cover	1	\$ 38.20	11 X
Rear chassis member @ 457.20	2	\$ 914.40	11 X
Rear chassis extension bracker @ 42.70	2	\$ 85.40	11 X
Rear chassis top panel @ 55.30	2	\$ 110.60	11 X
Rear number plate light @ 50.10	2	\$ 100.20	11 X

\$ 12,576.00

Less 20% \$ 2,515.20

Sub Total \$ 10,060.80

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
Rear windscreen sealant	1	\$ 100.00	new 40
Rear boot inner board clips @ 5	1 set	\$ 40.00	new 30
Rear end panel sealant	1	\$ 100.00	new 50
Rear end panel top garnish clips @ 5	4	\$ 20.00	new 1
Rear fender inner garnish clips	12	\$ 60.00	new 1
Rear number plate	1	\$ 45.00	new 1
Rear Bumber reverse sensor	1 set	\$ 350.00	shut 200
Sub Total		\$ 715.00	

LABOUR CHARGE	QTY	PRICE (\$)	REMARKS
To check wiring		\$ 120.00	20
Tuff kote		\$ 250.00	60
Remove and replace reverse sensor		\$ 150.00	60
Remove and refix cushion seat		\$ 250.00	60
To remove and replace spare part and penal beating		\$ 2,200.00	600
To spray painting and etc		\$ 1,800.00	800

Sub Total \$ 4,770.00

Grand Total \$ 15,180.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2630.2
202
210416
320
1570
401416
311