

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg;darren@sngahtee.com;janice@sngahtee.com

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2001808782-01	Date of Loss:	03/03/2023
Vehicle Reg. No.:	SKF8906Y	Driveable?	
Driver Age/Info:	54 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	AMRAN BIN ATAN	Contact No:	+6591762926
Driver:	AMRAN BIN ATAN		

Make/Model:	TOYOTA ESTIMA, 2.4 AERAS (A)	Vehicle Reg. Date:	15/10/2008
Vehicle Colour:	White		
Engine No:	2AZF162812	Chassis No:	ACR507063792
Odometer:	5 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) 6

Description of Accident/Loss AS PER POLICE RE

Remarks: VEHICLE IN WORKSHOP, PLS ARRANGE TO SURVEY

Present Location: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS

	Amount
Parts	3,522.00
Miscellaneous Items	0.00
Labour	1,810.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,332.00
+ GST 8.00% (S\$)	426.56
Nett Amount (S\$)	5,758.56

This claim is handled by: **SAMANTHA TAN YONG SING**

Generated using *Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2023)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Sng Ah Tee Motor & Panel Service Pte Ltd/SKF8906Y/06/03/2023 15:20	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE	0	0.00	*35.00 FS
2	1		*FRT BUMPER	0.00	0.00	*240.00 F
3	2		*FRT BUMPER RETAINER	0.00	0.00	*90.00 F
4	1		*FRT BUMPER LWR GRILLE	0.00	0.00	*90.00 F
5	1		*FRT BUMPER LWR OUTER CHROME TRIM	0.00	0.00	*140.00 F
6	1		*FRT BUMPER UPPER TOP BEAM	0.00	0.00	*150.00 F
7	1		*FRT BUMPER SPONGE	0.00	0.00	*60.00 F
8	1		*FRT BUMPER REINFORCEMENT	0.00	0.00	*150.00 F
9	1		*FRT BUMPER TOP SEAL	0.00	0.00	*45.00 F
10	10		*FRT BUMPER CLIP	0.00	0.00	*10.00 F
11	1		*FRT GRILLE ASSY	0.00	0.00	*190.00 F
12	1		*FRT GRILLE EMBLEM	0.00	0.00	*45.00 F
13	10		*FRT GRILLE CLIP	0.00	0.00	*20.00 F
14	1		*FRT BONNET	0.00	0.00	*240.00 F
15	2		*FRT BONNET HINGE	0.00	0.00	*80.00 F
16	10		*FRT BONNET INSULATOR CLIP	0.00	0.00	*20.00 F
17	2		*FRT HEADLAMP	0.00	0.00	*1,100.00 F
18	1		*AIRCON CONDENSER	0.00	0.00	*500.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	3,205.00
+ Margin on L,N Items 10.00% (\$\$)	317.00
Total Parts (\$\$)	3,522.00

Sng Ah Tee Motor & Panel Service Pte Ltd/SKF8906Y/06/03/2023 15:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS	New	750.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED ARAES	New	750.00
3	CHECK WIRING	New	30.00
4	TOP UP AIRCON GAS	New	100.00
5	TO DIAGNOSE & RESET FAULT CODE	New	180.00
Gross Labour Cost (S\$)			1,810.00

Sng Ah Tee Motor & Panel Service Pte Ltd/SKF8906Y/06/03/2023 15:20. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >