

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 08 Mar 2023

Preliminary Advice

Vehicle No	: SKF8906Y	Accident Date	: 03/03/2023
Make	: TOYOTA ESTIMA	Policy No.	: SP2001808782-01
Assignment Date	: 07/03/2023	Excess	: S\$600.00
Date of Inspection	: 08/03/2023 (Desktop Survey)	Est. Duration of Repair	: 4 days
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,332.00
Revised Amount	:S\$	2,063.00
Check Items (Estimated)	:S\$	2,404.50
Total	:S\$	4,467.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	49,000.00
COE / PARF Rebate	:S\$	18,864.00
Salvage Value	:S\$	
Margin for Repair	:S\$	30,136.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.