

Edward LKK

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Mar 2023)

Parts: M1-MPV TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/SKF8906Y/06/03/2023 15:20

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE	0	0.00	*35.00 F CUT
2	1		*FRT BUMPER	0.00	0.00	*240.00 F DT
3	2		*FRT BUMPER RETAINER	0.00	0.00	*90.00 F ?
4	1		*FRT BUMPER LWR GRILLE	0.00	0.00	*90.00 F CUT
5	1		*FRT BUMPER LWR OUTER CHROME TRIM	0.00	0.00	*140.00 F CRA
6	1		*FRT BUMPER UPPER TOP BEAM	0.00	0.00	*150.00 F ?
7	1		*FRT BUMPER SPONGE	0.00	0.00	*60.00 F ?
8	1		*FRT BUMPER REINFORCEMENT	0.00	0.00	*150.00 F ?
9	1		*FRT BUMPER TOP SEAL	0.00	0.00	*45.00 F ?
10	10		*FRT BUMPER CLIP	0.00	0.00	*10.00 F HEC
11	1		*FRT GRILLE ASSY	0.00	0.00	*190.00 F CRA
12	1		*FRT GRILLE EMBLEM	0.00	0.00	*45.00 F OTS
13	10		*FRT GRILLE CLIP	0.00	0.00	*20.00 F HEC
14	1		*FRT BONNET	0.00	0.00	*240.00 F EMC
15	2		*FRT BONNET HINGE	0.00	0.00	*80.00 F TXNN
16	10		*FRT BONNET INSULATOR CLIP	0.00	0.00	*20.00 F HEC
17	2		*FRT HEADLAMP	0.00	0.00	*1,100.00 F ?
18	1		*AIRCON CONDENSER	0.00	0.00	*500.00 F ?

F=Franchise part. S=SpcNett.

Sub Total (S\$) \$1645.00 3,205.00
+ Margin on L,N Items 10.00% (S\$) add 10% = \$1809.50 317.00
Total Parts (S\$) Snett \$257 3,522.00

Sng Ah Tee Motor & Panel Service Pte Ltd/SKF8906Y/06/03/2023 15:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS	New	400 750.00 ✓
2	TO PUTTY & SPRAY PAINTING ON AFFECTED ARAES	New	500 750.00
3	CHECK WIRING	New	30.00
4	TOP UP AIRCON GAS	new New ✓	100.00
5	TO DIAGNOSE & RESET FAULT CODE	New	180.00 X NN
Gross Labour Cost (\$\$)			6-10301 1,810.00

Sng Ah Tee Motor & Panel Service Pte Ltd/SKF8906Y/06/03/2023 15:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR 4 DAYS

- NOT AUTHORISE
- EXCESS \$600 ✓
- P/P OR L/S REPAIR
- SURVEY BY EDWARD TEL 62563561
- RESURVEY BEFORE PAINT FOR P/P REPAIR

total \$2874.50
 (4520/2) = \$2299.60
 2 \$2250-4's
 before ERM \$600
 or? 16 PERCENT . share
 14/6/2023

LKK Auto Consultant, hereby notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: