

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002406/KQP3M4**Date:** 10/04/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00118812201
Claimant Vehicle No :	PC9255S	Insured Vehicle No :	GBL5439Z
Date of Loss:	02/03/2023	Nature of Claim:	TP
		Claim No:	SNM23D201649/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC9255S	Engine No:	50329283042928
Make & Model:	MAN NL320F (A22), 10.5 D (A)	Chassis No:	WMAA22ZZ9B7001186
Reg. Date:	05/12/2011 (Man. Year: 2011)	Odometer:	749364 km
Colour:	Multi-colour		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70R22.5	Rear Tyre Size:	275/70R22.5 (D)
Front Left Side:	DURATURN 9 mm	Rear Left Side:	Giti 8/8 mm
Front Right Side:	DURATURN 9 mm	Rear Right Side:	Giti 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,336.70	8,180.00	10,156.70	55.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,000.00	4,200.00	1,800.00	30.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,336.70	12,380.00	11,956.70	49.13
Approved Total (Overridden) (S\$)		9,900.00		
Nett Amount (S\$)	24,336.70	9,900.00	14,436.70	59.32

INSPECTION

Date of Assignment:	05/04/2023	SERVE YOU MOTOR PTE LTD (HQ) BLK 5033 ANG MO KIO INDUSTRIAL PARK 2, #01-265 SINGAPORE 569536
Date Inspected:	08/03/2023 Inspected At:	
Estimated Period of Repair:	7.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 10 Apr 2023)	
Parts:	N/A	MAN NL320F (A22) 10.5 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC9255S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH ARCH PANEL	Repair	1,850.00 FL	*- FL
2	1		*RH A BODY PANEL 2	Repair	2,450.00 FL	*- FL
3	1		*RH INDICATOR LAMP	Serviceable	188.00 FL	*- FL
4	1		*RH BODY CENTRAL PANEL	Repair	1,680.00 FL	*- FL
5	1		*REAR RH COMPARTMENT	Warped/Bent	2,200.00 FL	*2,200.00 FL
6	2		*REAR RH COMPARTMENT SUPPORT BAR	Serviceable	400.00 FL	*- FL
7	1		*REAR RH ARCH PANEL	Bent	1,680.00 FL	*1,200.00 FL
8	1		*REAR RH SECTION DOOR WITH GRILLER ASSY	Warped/Cracked	3,500.00 FL	*1,800.00 FL
9	1		*SET RH COMPARTMENT DOOR LOCK	Repair	238.00 FL	*- FL
10	1		*BODY RH COMPANY ARTWORK	Necessary	4,500.00 FS	*3,200.00 FS
11	1		*BATTERY BOX AND EXCURSION BUS ARTWORK	Necessary	80.00 FS	*40.00 FS
12	2		*WINDSCREEN SEAL	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,046.00	8,440.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	709.30	260.00
Total Parts (\$\$)	18,336.70	8,180.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	3,800.00	2,400.00
2	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY ON ACCIDENT PORTION	New	2,200.00	1,800.00
Gross Labour Cost (S\$)			6,000.00	4,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >