

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT HSBC LIFE (SINGAPORE) PTE LTD CS3/HSB23002407/Twp3m4 Ref: 10 MARINA BOULEVARD #48-01 MARINA BAY Date: 10/03/2023 FINANCIAL CENTRE TOWER 2 SINGAPORE ATTN: TEO KITTY Code: HSB Policy Particulars :- (THIRD PARTY CLAIM) 1. SH 6843C FBD 4274E Insured Veh. Veh. Inspected VFX/P2419138 0.00 Policy No. Coverage (\$) S3M04JKW 0.00 Claim No. Excess (\$) TEO KITTY 07/03/2023 **Assign Date** Assign From Vehicle Particulars & Condition 2. YAMAHA T135 135 Make & Model C.C **HIDDEN Engine No.** Year of Reg. 2009 **RED** Chassis No. 5YP009534 Colour Odometer **IN ORDER** Steering **IN ORDER** Modification NIL **Brakes** GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 70/90R17 **MAXXIS** 5 mm L/H Front Tyre mm 80/90R17 **MAXXIS** R/H Rear Tyre 5 mm L/H Rear Tyre mm **Description of Damages** 4. THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. 5. **General Information** 17/02/2023 Inspect Date / Time 07/03/2023 (02:50 PM) **Accident Date** Survey held at TUNE IN MOTOR BLK 1016 YISHUN PARK A #01-214 SINGAPORE 768758 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500 5b. **Estimate Days of Repair**

Report Ref No. CS3/HSB23002407/Twp3m4

Inspected By

MOHAMAD TAUFIKH

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

5 Working Days

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.