

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Lim

Date: 08 Mar 2023

**Preliminary Advice**

Vehicle No	: SLM7789B	Accident Date	: 04/03/2023
Make	: TOYOTA VOXY	Policy No.	: SP2001555549
Assignment Date	: 07/03/2023	Excess	: S\$600.00
Date of Inspection	: 8/3/2023	Est. Duration of Repair	: 6
Inspection At	: ESTEEM PERFORMANCE PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,018.03
Revised Amount	:S\$	5,943.92
Check Items (Estimated)	:S\$	3,409.65
Total	:S\$	9,353.57

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	139,000.00
COE / PARF Rebate	:S\$	42,733.00
Salvage Value	:S\$	
Margin for Repair	:S\$	96,267.00

**Remarks** ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. ( X ) Other comments : Part by part repair as there is no 2nd hand parts available

Accordingly to surveyor, damages are consistent to the nature of the accident.

According to repairer they are unable to submit cost price, cause they not authorise workshop.