

ADVANCE AUTO GARAGE

VEHICLE DETAILS

VEHICLE NO : SNA4328H 2021 JUNE
 VEHICLE MODEL : VOLKSWAGEN TIGUAN
 CHASSIS NO : WVGZZZ5NZLW389873

To Liberty.
 Veron.

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE LAMP <i>new</i>	2	\$ 68.00	\$ 136.00
2	REAR BUMPER <i>Delud</i>	1	\$ 1,729.00	\$ 1,729.00
3	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 78.00	\$ 156.00
4	REAR BUMPER REFLECTOR INNER <i>3 Cracked</i>	2	\$ 87.00	\$ 174.00
5	REAR BUMPER REFLECTOR OUTER	2	\$ 79.00	\$ 158.00
6	REAR BUMPER CHROME MOULDING CENTRE <i>Cracked</i>	1	\$ 245.00	\$ 245.00
7	REAR BUMPER CHROME MOULDING SIDE <i>in</i>	2	\$ 189.00	\$ 378.00
8	REAR BUMPER REINFORCEMENT <i>Delud</i>	1	\$ 906.00	\$ 906.00
9	REAR BUMPER INNER FRAME <i>Cracked</i>	1	\$ 198.00	\$ 198.00
10	REAR BUMPER CENTRE <i>Distorted</i>	1	\$ 429.00	\$ 429.00
11	REAR BUMPER LOWER DIFFUSER <i>Delud</i>	1	\$ 601.00	\$ 601.00
12	REAR BUMPER SENSOR <i>3 Distorted</i>	4	\$ 262.00	\$ 1,048.00
13	REAR BUMPER I <i>Sensor Holder new</i>	4	\$ 24.00	\$ 100.00
14	REAR END PANEL OUTER <i>3 Distorted</i>	1	\$ 569.00	\$ 569.00
15	REAR END PANEL INNER	1	\$ 395.00	\$ 395.00
16	REAR END PANEL TOP GARNISH <i>Cracked</i>	1	\$ 294.00	\$ 294.00
17	TAILLAMP <i>Cracked</i>	2	\$ 651.00	\$ 1,302.00
18	TAILLAMP LOWER BRACKET <i>Cracked</i>	2	\$ 62.00	\$ 124.00
19	TAILGATE <i>Distorted</i>	1	\$ 3,188.00	\$ 3,188.00
20	TAILGATE LOCK <i>Dist</i>	1	\$ 209.00	\$ 209.00
21	TAILGATE WEATHERSTRIPE <i>new</i>	1	\$ 249.00	\$ 249.00
22	TAILGATE INNER TRIM BOARD <i>Cracked</i>	1	\$ 448.00	\$ 448.00
23	TAILGATE REFLECTOR <i>Cracked</i>	2	\$ 397.00	\$ 794.00
24	TAILGATE GLASS MOULDING <i>new</i>	1	\$ 194.00	\$ 194.00
25	TAILGATE CAMERA <i>Dist</i>	1	\$ 1,041.00	\$ 1,041.00
26	VOLSWAGEN LOGO <i>new</i>	1	\$ 116.00	\$ 116.00
27	TIGUAN WORDING	1	\$ 110.00	\$ 110.00
28	REAR FENDE INNER TRIM BOARD <i>Cracked</i>	2	\$ 588.00	\$ 1,176.00
29	FLOOR PANEL <i>Ris</i>	1	\$ 1,689.00	\$ 1,689.00
30	FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 794.00	\$ 794.00
31	REAR EXHAUST PIPE <i>3 new</i>	1	\$ 1,127.00	\$ 1,127.00
32	REAR EXHAUST PIPE MOUNTING <i>new</i>	1	\$ 45.00	\$ 45.00
33	RAER EXHAUST PIPE GASKET <i>new</i>	1	\$ 38.00	\$ 38.00
34	REAR EXHAUST PIPE HEAT SHIELD	1	\$ 149.00	\$ 149.00

14840
 13386

TOTAL PRICE: \$ 20,309.00
 LESS 5% *10%* \$ 1,015.45
 SUB TOTAL PRICE: \$ 19,293.55

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
--	-------	-----	------------	-------

1	REAR NUMBER PLATE <i>Dented</i>	1	\$	30.00	\$	30.00	✓
2	REAR NUMBER PLATE HOLDER <i>Del 2</i>	1	\$	30.00	\$	30.00	✓
3	REAR BUMPER CLIPS <i>nr</i>	1 SET	\$	50.00	\$	50.00	✓
4	REAR END PANEL TOP GARNISH CLIPS <i>nr</i>	1 SET	\$	20.00	\$	20.00	✓
5	REAR END PANEL SEALANT <i>nr</i>	1	\$	60.00	\$	60.00	✓
6	TAILGATE INNER TRIM BOARD CLIPS <i>nr</i>	1 SET	\$	30.00	\$	30.00	✓
7	TAILGATE GLASS SEALANT <i>nr</i>	1	\$	60.00	\$	60.00	✓
8	REAR FENDER INNER TRIM BOARD CLIPS <i>nr</i>	2 SET	\$	30.00	\$	60.00	30. ✓
			TOTAL :		\$	340.00	

310

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,800.00	<i>1200</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	<i>1100</i>	
3	WIRING CHECK	\$ 100.00	<i>30</i>	
4	TO APPLY TUFF COAT	\$ 150.00	<i>80</i>	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	<i>50</i>	
6	TO REMOVE REAR CAMERA	\$ 100.00	<i>50</i>	
7	TO REMOVE REAR VIDEO RECORDER	\$ 100.00	<i>50</i>	
8	TO REMOVE UPHOLSTERY & REAR SEAT	\$ 300.00	<i>80</i>	
9	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	<i>80</i>	
10	TO REMOVE TAILGATE GLASS	\$ 180.00	<i>120</i>	
11	TO REMOVE REAR EXHAUST PIPE	\$ 150.00	<i>x</i>	
12	TO PERFORM DIAGNOSTIC TEST	\$ 200.00	<i>100</i>	

\$ 4,930.00

2840

ESTIMATE REPORT

TOTAL PARTS COST: \$ 19,633.55

TOTAL LABOUR COST: \$ 4,930.00

TOTAL REPAIR COST: \$ 24,563.55

total: 16506

4/5: 13.2k

08 Days

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

13.2k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: