

(08/11/13) wef

ASS - REC. BY: mm

REF:

CS/U0123002412/RV3

983F

CSE-2030/86P

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLJ 2710 Bat Workshop m/s ARCof 48, Port Limerick Rd EAST A02-146

Insured:

W01

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

91K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 64K

Veh No:

SLJ 2710 B

Yr Regn:

2011 12WType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MERCEDES Benz E 250 Cuic.c 1796

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

23 8695

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2120472A 401620Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

01/03/23

D.O.I.

07/03/23

Survey held at

ARC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

1)

Date/Time, File Return to?

☐

: Final Report

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Transportation:

S + RS, SI

Photos

Others

Report Format :

Lump Sum / I.B.I.: (\$

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2303-160-TG

DATE : 7-Mar-2023

POLICY NO. :

VEHICLE REG. NO. : **SLJ2710B**

VEHICLE MAKE : MERCEDES BENZ E 250CGI

REG DATE : 30/6/2011

FOR SURVEYOR

TO Motor Claim Department
United Overseas Insurance Ltd
146 Robinson Road, #02-01
UOI Building
Singapore 068909

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Front Bumper (212 880 1340 9999) <i>Repair de /</i>	1	\$ 1,756.00	\$ 1,756.00
3	Front Bumper Carrier LH (212 885 2865) <i>X</i>	1	\$ 116.00	\$ 116.00
4	Front Bumper Carrier RH (212 885 2965) <i>X</i>	1	\$ 116.00	\$ 116.00
5	Front Bumper Side Retainer LH (212 889 1195) <i>X</i>	1	\$ 32.00	\$ 32.00
6	Front Bumper Side Retainer RH (212 889 1295) <i>X</i>	1	\$ 32.00	\$ 32.00
7	Front Bumper Lower Grille (212 885 0523) <i>?</i>	1	\$ 117.00	\$ 117.00
8	Front Bumper Number Plate Garnish (212 817 0078) <i>cm /</i>	1	\$ 289.00	\$ 289.00
9	Front Bumper Chrome LH (212 885 0321) <i>cm /</i>	1	\$ 163.00	\$ 163.00
10	Front Bumper Chrome RH (212 885 0421) <i>cm /</i>	1	\$ 163.00	\$ 163.00
11	Front Bumper Towing Cover (212 885 0126 9999) <i>mis /</i>	1	\$ 105.00	\$ 105.00
12	Front Bumper Center Bracket (212 885 2765) <i>?</i>	1	\$ 158.00	\$ 158.00
13	Front Bumper Sponge (212 885 1837) <i>?</i>	1	\$ 193.00	\$ 193.00
14	Front Bumper Sponge LH (212 885 0537) <i>?</i>	1	\$ 108.00	\$ 108.00
15	Front Bumper Sponge RH (212 885 0637) <i>?</i>	1	\$ 108.00	\$ 108.00
16	Front Bumper Reinforcement (212 620 1500) <i>?</i>	1	\$ 720.00	\$ 720.00
17	Front Grille (212 880 0983 7246) <i>cm /</i>	1	\$ 1,440.00	\$ 1,440.00
18	Front Grille Emblem (221 817 0016) <i>cm /</i>	1	\$ 72.00	\$ 72.00
19	Front Bonnet (212 880 0157) <i>repair</i>	1	\$ 2,870.00	\$ 2,870.00
20	Front Bonnet Catch (212 880 0064) <i>X</i>	1	\$ 110.00	\$ 110.00
21	Front Bonnet Emblem (221 880 0086) <i>cm /</i>	1	\$ 158.00	\$ 158.00
22	Front Bonnet Actuator LH (212 906 6201) <i>act /</i>	1	\$ 502.00	\$ 502.00
23	Front Bonnet Actuator RH (212 906 6301) <i>act /</i>	1	\$ 502.00	\$ 502.00
24	Front Headlamp LH (212 820 8361) <i>?</i>	1	\$ 1,350.00	\$ 1,350.00
25	Front Headlamp RH (212 820 8461) <i>?</i>	1	\$ 1,350.00	\$ 1,350.00
26	Front Brace Panel (212 898 0232) <i>?</i>	1	\$ 73.00	\$ 73.00
27	Front Support Panel (212 620 1100) <i>X</i>	1	\$ 204.00	\$ 204.00
28	Rear Bumper (212 880 4740 9999) <i>de /</i>	1	\$ 1,896.00	\$ 1,896.00
30	Rear Bumper Side Retainer LH (212 880 1330) <i>X</i>	1	\$ 72.00	\$ 72.00
31	Rear Bumper Side Retainer RH (212 880 1430) <i>X</i>	1	\$ 72.00	\$ 72.00
32	Rear Bumper Chrome LH (212 885 2121) <i>cm /</i>	1	\$ 216.00	\$ 216.00
33	Rear Bumper Chrome RH (212 885 2221) <i>cm /</i>	1	\$ 216.00	\$ 216.00

48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2303-160-TG
DATE : 7-Mar-2023
POLICY NO. :
VEHICLE REG. NO. : SLJ2710B
VEHICLE MAKE : MERCEDES BENZ E 250CGI
REG DATE : 30/6/2011
FOR SURVEYOR

TO Motor Claim Department
United Overseas Insurance Ltd
146 Robinson Road, #02-01
UOI Building
Singapore 068909

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
34	Rear Bumper Ctr Chrome (212 885 2021) <i>cm /</i>	1	\$ 254.00	\$ 254.00
35	Rear Bumper Towing Cover (212 885 0326 9999) <i>mis /</i>	1	\$ 105.00	\$ 105.00
36	Rear Bumper Lower Garnish (212 885 1925 9999) <i>de /</i>	1	\$ 678.00	\$ 678.00
37	Rear Bumper Outer Sensor LH (212 542 0018 9999) <i>X</i>	1	\$ 368.00	\$ 368.00
38	Rear Bumper Outer Sensor RH (212 542 0018 9999) <i>mis X</i>	1	\$ 368.00	\$ 368.00
39	Rear Bumper Ctr Sensor LH (212 542 0018 9999) <i>X</i>	1	\$ 368.00	\$ 368.00
40	Rear Bumper Ctr Sensor RH (212 542 0018 9999) <i>mis /</i>	1	\$ 368.00	\$ 368.00
41	Rear Bumper Reinforcement (212 610 2014) <i>lf /</i>	1	\$ 1,155.00	\$ 1,155.00
42	Rear Boot (212 750 0975) <i>lf /</i>	1	\$ 3,556.00	\$ 3,556.00
43	Rear Boot Weatherstrip (212 750 0198) <i>mi /</i>	1	\$ 266.00	\$ 266.00
44	Rear Boot Logo CGI (209 817 0515) <i>mi /</i>	1	\$ 192.00	\$ 192.00
45	Rear Boot Emblem (212 817 0016) <i>mi /</i>	1	\$ 76.00	\$ 76.00
46	Rear Boot Logo E250 (124 817 6115) <i>mi /</i>	1	\$ 153.00	\$ 153.00
47	Rear Boot Chrome (212 743 0282) <i>?</i>	1	\$ 226.00	\$ 226.00
48	Rear Boot Hinge LH (212 750 0328) <i>X</i>	1	\$ 739.00	\$ 739.00
49	Rear Boot Hinge RH (212 750 0428) <i>X</i>	1	\$ 739.00	\$ 739.00
50	Rear Boot Lamp LH (212 906 0158) <i>X</i>	1	\$ 538.00	\$ 538.00
51	Rear Boot Lamp RH (212 906 0258) <i>sun /</i>	1	\$ 538.00	\$ 538.00
52	Rear Boot Lock <i>cut /</i>	1	\$ 410.00	\$ 410.00
53	Rear Tail Lamp LH (212 906 6601) <i>X</i>	1	\$ 742.00	\$ 742.00
54	Rear Tail Lamp RH (212 906 6701) <i>cm /</i>	1	\$ 742.00	\$ 742.00
55	Rear End Panel (212 640 0300) <i>lf /</i>	1	\$ 1,576.00	\$ 1,576.00
56	Rear End Panel Top Garnish (212 690 3100 9051) <i>cm /</i>	1	\$ 205.00	\$ 205.00
57	Front Seat Head Rest RH (212 970 7850 9E43) <i>?</i>	1	\$ 1,156.00	\$ 1,156.00
Parts Less 10%				\$ (3,079.70)
Total Spare Parts				\$ 27,717.30
SPECIAL NETT				
58	Front Bumper Clips <i>mi /</i>	10	\$ 9.00	\$ 90.00 <i>80</i>
59	Rear Bumper Clips <i>mis X</i>	10	\$ 10.00	\$ 100.00 <i>X</i>
60	Coolant 4L <i>X</i>	1	\$ 40.00	\$ 40.00 <i>X</i>
Total Special Nett				\$ 230.00

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2303-160-TG

DATE : 7-Mar-2023

POLICY NO. :

VEHICLE REG. NO. : **SLJ2710B**

VEHICLE MAKE : MERCEDES BENZ E 250CGI

REG DATE : 30/6/2011

FOR SURVEYOR

TO Motor Claim Department
United Overseas Insurance Ltd
146 Robinson Road, #02-01
UOI Building
Singapore 068909

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	LABOUR			
61	Remove, Refit and Align Affected Accident Area incl. Repair	1	\$ 1,400.00	\$ 1,400.00
62	Spray painting (Whole Front & Rear)	1	\$ 1,400.00	\$ 1,400.00
63	Remove and Replace Front Head Rest	1	\$ 150.00	\$ 150.00
64	Reset ECU, ABS and SRS	1	\$ 200.00	\$ 200.00
65	Remove & Refit aircon condenser, pipes, radiator, vacuum & refill gas (R134)	1	\$ 120.00	\$ 120.00
66	Remove & Replace Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
67	Check and Rectify Electrical Wiring	1	\$ 50.00	\$ 50.00
Total Labour				\$ 3,400.00
Amount Before Excess				\$ 31,347.30
Add GST @ 8%				2,507.78
Total Amount Payable				\$ 33,855.08

Estimate prepared by: JAMES

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour \$ 3,400.00
Amount Before Excess \$ 31,347.30
Add GST @ 8% 2,507.78
Total Amount Payable \$ 33,855.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

James
Hp 900 10568
9 days
L/S
07/03/23 @ 1540
Resy after repair

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 983F

Vehicle Details

Vehicle No.: SLJ2710B
Vehicle to be Exported: No
Intended Deregistration Date: 09 Mar 2023
Vehicle Make: MERCEDES BENZ
Vehicle Model: E 250CGI
Primary Colour: Grey
Manufacturing Year: 2011
Engine No.: 27186030209745
Chassis No.: WDD2120472A409020
Maximum Power Output: 150.0 kW (201 bhp)
Open Market Value: \$52,909.00
Original Registration Date: 30 Jun 2011
First Registration Date: 30 Jun 2011
Transfer Count: 1
Actual ARF Paid: \$52,909.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Sep 2030
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
PQP Paid: \$34,935.00
COE Rebate Amount: \$26,405.00
Total Rebate Amount: \$26,405.00

Mercedes-Benz E-Class E250 CGI (COE till 05/2031)

Overview

[Insurance](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)

Price **\$105,000** [Get Pre-approved Loan.](#)

Depreciation ⓘ **\$12,750 /yr** **Reg Date** **01-Jul-2011**
(8yrs 2mths 22days COE left)

Mileage **159,000 km (13.6k /yr)** **Manufactured** ⓘ **2011**

Road Tax ⓘ **\$1,169 /yr** **Transmission** **Auto**

Dereg Value ⓘ **\$40,931 as of today (change)** **OMV** ⓘ **\$52,909**

COE ⓘ **\$49,716** **ARF** ⓘ **\$52,909**

Engine Cap **1,796 cc** **Power** **150.0 kW (201 bhp)**

Curb Weight ⓘ **1,650 kg** **No. of Owners** ⓘ **2**

Type of Vehicle **Luxury Sedan**