

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 05 Jul 2023

**Preliminary Advice**

|                    |                                                                                                             |                         |              |
|--------------------|-------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : YP1175S                                                                                                   | Accident Date           | : 04/03/2023 |
| TP Vehicle No      | : GV555S                                                                                                    | Assignment Date         | : 07/03/2023 |
| Make               | : ISUZU NHR69E                                                                                              | Est. Duration of Repair | : 5          |
| Date of Inspection | : 07/03/2023                                                                                                |                         |              |
| Inspection At      | : BIFROST AUTO PTE LTD (KAKI BUKIT)<br>8 KAKI BUKIT AVE 4, #01-49, PREMIER @ KAKI BUKIT<br>SINGAPORE 415875 |                         |              |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 21,451.00 |
| Revised Amount              | :S\$ | 6,444.60  |
| Check Items (Estimated)     | :S\$ | 297.60    |
| Total                       | :S\$ | 6,742.20  |

|                 |      |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.