



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC23002422/Awy3e2

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 11/04/2023

ATTN: AZHARI

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJK 769P	Veh. Inspected	SLK 8453Z
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1211907-002	Excess (\$)	0.00
Assign From	JESS TOH	Assign Date	07/03/2023

2. Vehicle Particulars & Condition

Make & Model	HONDA HRV	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JHMRU1810GX201759	Colour	WHITE
Odometer	111928 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	FALKEN	6 mm
L/H Front Tyre	215/60 R16	FALKEN	6 mm
R/H Rear Tyre	215/60 R16	FALKEN	6 mm
L/H Rear Tyre	215/60 R16	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/02/2023	Inspect Date / Time	07/03/2023 (10:34 AM)
Survey held at	1 KAKI BUKIT AVENUE 6 #02-25 AUTOBAY @ KAKI BUKIT		
Repairer	LC AUTOMOTIVE		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days