

LC AUTOMOTIVE

25 KAKI BUKIT ROAD 4 #05-26 Synergy @ KB Singapore 417800

XYF & S BUILDER PTE LTD
25 KAKI BUKIT ROAD 4
05-26 SYNERGY @KB
Singapore 417800

TP INC.

Xin Yu

07th MARCH 2023

JHMR41810G X201759.

Accident date: 28th FEB 2023

Estimated repair cost for vehicle no: SLK8453Z HONDA HRV 2017

S/n	Qty	Items	U/price	Amount	
1	2	Front head lamp <i>LH cracked</i>	\$1,785.20	\$3,570.40	1785.20.
2	2	head lamp bracket <i>LH cracked</i>	\$155.00	\$310.00	55
3	1	Front bumper <i>Deformed</i>		\$1,150.00	524
4	1	Front bumper reinforcement <i>Bent</i>		\$688.20	395
5	10	Front bumper clips <i>New</i>	\$5.00	\$50.00	30
6	2	Front Bumper Fog lamp <i>3 New</i>	\$285.20	\$570.40	X
7	2	Front Bumper Fog lamp cover <i>3 New</i>	\$175.20	\$350.40	X
8	1	Front Grille <i>cracked</i>		\$452.20	385
9	1	Front Grille emble logo <i>New</i>		\$95.00	58.
10	1	Front center top garnish <i>New</i>		\$488.20	X
11	1	front grille centre moulding <i>cracked</i>		\$212.20	✓
12	10	Front Grille clips <i>New</i>	\$5.00	\$50.00	30.
13	1	front number plate <i>New</i>		\$50.00	X.
14	2	front number plate lamp <i>New</i>	\$112.20	\$224.40	X.
15	1	front bumper towing cover <i>New</i>		\$75.00	X.
16	1	Rear Boot Lid <i>Dented</i>		\$1,255.20	1100-878
17	2	Rear Boot Lid Hinges <i>New</i>	\$155.20	\$310.40	X.
18	1	Rear boot lid emble logo <i>New</i>		\$85.00	40.
19	1	Rear boot lid HRV logo <i>3 New</i>		\$55.00	✓
20	1	boot lid i-vtec logo <i>3 New</i>		\$55.00	✓
21	2	Rear Boot Lid side reflector <i>cracked</i>	\$425.20	\$850.40	✓
22	1	Rear boot lid inner rubber <i>cut</i>		\$285.20	180
23	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$284.20	189.
24	1	Rear Boot Lid Number Plate <i>New</i>		\$50.00	X
25	2	Rear Boot Lid Number Plate Lamp <i>New</i>	\$75.00	\$150.00	X.
26	1	Rear Boot Lid center moulding <i>cracked</i>		\$412.20	341
27	10	Rear Boot Lid Inner Trim board clips <i>New</i>	\$5.00	\$50.00	30
28	1	Rear Boot Lid Inner Trim board <i>cracked</i>		\$655.20	258.
29	2	Rear tail lamp <i>cut</i>	\$552.10	\$1,104.20	✓
30	2	tail lamp lower panel <i>Deformed</i>	\$388.20	\$776.40	390
31	1	Rear end panel <i>Dented</i>		\$655.20	397
32	1	Rear End Panel Top Garnish <i>Deformed</i>		\$215.30	✓
33	1	Rear Bumper <i>Distorted</i>		\$950.00	492
34	2	Rear Bumper Side Reflector <i>New</i>	\$66.00	\$132.00	X.
35	1	Rear Bumper reverse sensor <i>Damaged</i>		\$350.00	200.
36	2	rear bumper side retainer <i>New</i>	\$165.20	\$330.40	64.
37	8	Rear bumper clips <i>New</i>	\$5.00	\$40.00	✓
38	2	rear fender inner cowling <i>New</i>	\$215.20	\$430.40	X.
39	1	Rear spare tire panel sealant <i>New</i>		\$280.00	X.
40	1	Rear spare tire panel top cover <i>Deformed</i>		\$452.00	299.
41	1	rear windscreen inner seal <i>3 New</i>		\$155.20	58.
42	2	rear windscreen inner rubber <i>cracked</i>		\$255.00	112
2		Rear Fender Arc Garnish <i>154</i>	308		1037830
2		Rear Fender Arc Garnish Clips <i>20</i>	40		830264
1		Tools Sponge Tray <i>208</i>	208		
Subtotal :-				\$18,960.30	

Labour charges

To remove & re-fix cushion

~~\$120.00~~ 80

To Remove & refix rear windscreen

~~\$120.00~~ ✓

Gum

~~\$50.00~~ ✓

To Remove & refix reverse Sensor

~~\$120.00~~ 50

Tuff kote

~~\$150.00~~ 80

To Check Wiring System

~~\$80.00~~ 60.

Panel beating

~~\$1,600.00~~ 1200

Spray painting

~~\$1,600.00~~ 1000.

To remove rear camera

100.50

Subtotal :-

\$3,840.00

Total:-

\$22,800.30

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling.

L/S 08 Days

Total: 10992.64

L/S: 8.7K

8.7K